LAND CORNER RECORDATION CERTIFICATE Eiling Daguingmant at 5 -4 34 444 4

For corners in Baraga	r ming requirement of Act 74, Mich. P.A. 1		L 1970
(County)	Located In:	Corner Code ≠#	
1. Public Land Survey	T 47N R 34W T 47N R 34W T		
2. Properly Controlling in Section	T R		
Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No , F	Recorded Plat		A B C D E F G H J J K I
g. Stephan J. Szyszkoski do hereby certify that under red in lines 1 and 2 above were in current manual of survey instruManagement or by a decree of a above were in conformance will Court of Law; established, reexpressed below:	in a field survey on 13 July purements of P.A. 74, Michigan P. An conformance with regulations are actions of the United States Departs Court of Law and/or that the correl hither News of the Michigan Roard.	rch 23, 1994 If 12, 1994 of 1970, the corner points mentione of the therefore as required in the therefore, Bureau of Landrope of the Interior, Bureau of Landrope of the Landrope of the Corner of	od 6 18 17 16 15 14 13 15 14 15 15 15 16 15 15 16 15 15 16 15 16 15 16 15 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
A Description of oxidinal a	Dogument and seesand		13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1

A. Description of original monument and accessories and/or subsequent restoration:

(L3) Quarter corner common to Sections 1-12. Corner established in 1852 by Z.B. Searles: Set quarter Sec. post, Hemlock 12 S28E 14, Newlock 10 MOTE 12. Corner recorded by Michigan Dept. State Highways and Transportation as found 1.5" iron pipe in 1958 and rewitnessed: 3' Balsam S80W 9.25', 3' spruce S60E 4.75', 5' Balsam M40W 8.04'. Found no subsequent record. (L1) Quarter corner common to Section 1 747M-R34W and Section 36 748M-R34W. Corner restored and recorded by A.O. Enger, RLS in 1988: 1°10 from pipe with 4° aluminum cap set inside a 1 1/2° ID from pipe. MBIs marked in 1988 were Red Maple 10 852E 63 links, Red maple 16 HOSE 40.5 links. Distances shown on the 1968 record are 40.19 ch. east and 40.10 chains west to monumented corners. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L3) Original monument not recovered. Found a 1.5° iron pipe leaning and loose in rocky soil. Removed the pipe and reset it vertically and in accord with the 1958 MBTs: \$71M 9.25' found neil in 8' belsem, I cut this tree down at BH, M36W 6.04' found neil in 6' dead balsam. The 1958 spruce was recovered (now 10' dia.) at record bearing and distance but meas, nail was not chopped out. This tree was re-marked as shown below. Sat the pipe firm in a mound of rock. Possible remains of the original Hemlock BY \$28E were recovered - a rolling windthrown stump at record bearing and distance with no markings visible. No trace of the other OBI. Determined the pipe to be 2838.65' sest and 2832.36' wast of adjacent monumented section corners and 3.76' South of a straight line between. I accepted the pipe as the best available evidence of the position of the original corner. Marked new Bis as described below. (L1) found and accepted the 1966 monument as described at record bearing and distance from the remains of the two MBTs - the Maple SE dead and down, the Maple ME now a stump cut low. Marked four new bearing trees as desribed below. The corner is 38' north of a rock

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L3) Found 1.5° dim. from pipe. Alezed and scribed the following new bearing trees: 18" Hemlock M28E 55.5" 8' Cedar 528E 28.8' "1/45 NBT" 13' Cadar 586W 44.8' "1/45 NBT" Bearings are magnetic. Decl 2.5 deg W.

(L1) Found 1" pipe with 4" MORR cap set inside a 1.5° ID from pipe. Blazed and scribed the following new bearing trees: 17" Coder \$34E 65.0" "1/48 NBT" "1/48 ABT"

5" Sugar 5897 29.6' 4' Sugar N26W 31.8' 1/48 MBT" 12" twin Y. Birch M82E 46.9" "1/45 M8T" Bearings are magnetic. Corner lies at north side of a 24" Maple with old blaze facing, squared and marked "1/4 S1 836".

STEPHAN J. SZYSZKOSKI LAND SURVEYOR

Dec1. 2.5 deg W. Surveyor's Michigan License No __33986