## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Chippewa		Located In:	Corner Code ≠#	
_	(County)		Comer Code 44	
1.	Public Land Survey	T <u>44N R 1N</u>		
		T <u>440</u> R <u>in</u>		
		T R	<del></del>	
		T R	<del></del>	
2	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		

Register of Deeds Stamp & File Number

Lot	No.		,	Recorded	Plat	
	Lot	Lot No.	Lot No	Lot No,	Lot No, Recorded	Lot No, Recorded Plat

5. Private Claims

Property in Sec.

E4 October 24, 1994

t, <u>Staphan J. Szyszkoski</u>, in a field survey on <u>F3 December 06, 1994</u>, 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (E3) Corner common to Sections 4-5-8-9. Original corner established by James Mullett in 1845 as follows: Set post corner of sections 4,5,8,9. Birch 24 M46E 54, Sugar 24 S50W 20. Found no subsequent record.
- (E4) Quarter corner common to Sections 8-9. Original corner established by James Mullett in 1845 as follows: Set quarter section post, Sugar 12 N46E 17, Sugar 12 S36N 33. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(£3) Original post and accessories not recovered. Found no evidence of the position of the original corner on the ground. Reastablished the corner proportionate to U.S. measure between section corners 5225.93° north (rec.=80.19 ch), 5254.09° east (rec.=79.85 ch), 5213.52° south (rec.=80.00 ch), and 5275.81° west (rec.=80.18 ch). At the position for the corner, I placed a 1°I.D.x36° iron pipe capped with a 4° diameter cast aluminum MDNR tablet, appropriately stamped.

(E4) Original post and accessories not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner proportionate to U.S. measure, being equidistant and on a straight line between section corners 2606.76' north and south. At the position for the corner, I placed a 1°I.D.x36" iron pipe capped with a 4" diameter cast aluminum MDNR tablet, appropriately stamped.

C. (ES) Set a I IV iron pipe with a 4 NONR (E4) Set a I ID iron pipe with a 4" MDNR

6 W. Pine M21E 19.15' "S4 MBT"
6" Clump Maple S40E 11.45' "S9 MBT"
4" W. Pine S27M 15.8' "S8 MBT"
Placed a 6" squared and scribed cedar post adjacent. Bearings are magnetic.

cap. Blazed, scribed, and set measuring nails with tags in the following new bearing trees:

4" Cherry S13M 10.4" "1/4S MBT"
10" Oak S19M 38.2" "1/4S MBT"
5" Cherry S69M 22.7" "1/4S MBT"
10" Spruce M78M 28.65" "1/4S MBT"
Placed a 5" squared and scribed cedar post adjacent. Bearings are magnetic.

STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986

Signed by Stephan J. Szysepali

\_\_ Date \_\_\_ 2-7-95