LAND CORNER RECORDATION CERTIFICATE

F	or corners in Dickinson	riling nequirement of Act 74, Mich.	
٠ _	(County)	Located In:	Corner Code ≠#
1	Public Land Survey	T 42H R 28H	F5
٠,	•	T R	
. :		ļ H	
2	. Properly Controlling in Section	S 16 T 42NR 28N S 16 T 42NR 28N	1 3
1	Miscellanaous		

Register of Deeds Stamp & File Number

4. Lot No. . Recorded Pla

5. Private Claims

Property in Sec

I, _Stephan J. Szyszkoski , in a field survey on _ Movember 23, 1992 , 19 _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F5) Quarter corner common to Sections 9-16. Corner previously recorded by Frank J. Bray RLS, in 1967 as monumented by a 1° iron pipe with a 4° aluminum cap and the following MBTs: 6° M. Birch (1/45) (MBT) MB6W 25 links, 6° Aspen (1/45) (MBT) 835W 35 links. Found no subsequent record.

(1) West 1/16 corner between sections 16-9. Corner previously recorded by Frank J. Bray RtS, in 1967 as monumented by a 1° iron pipe with 4" aluminum cap and the following mitnesses: 6" aspen (MI/16) (8T) M39E 07.5 links, 20" M. Pine (8T) 504E 141 links. Found no subsequent record.

(3) North 1/16 corner between sections 16-17. Corner previously recorded by Frank J. Bray ALS, in 1967 as monumented by 1° iron pipe with 4° aluminum cap and the following witness: 16 M. Pine (8T) N63. 40 links. Bray also motes This corner was placed at old fence corner which checks well with being on line and midway between 1/4 cor to south and sec. cor. to north".

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

(F5) Found monument as described above. The 1967 STs were not recovered. Harked four new bearing trees as described below. (1) found monument as described above. Corner falls in clearcut area. Previous bearing trees not recovered. Harked four new bearing trees as described below.

(3) Record monument was not recovered. Found dead 16" W. Pine with BT blaze M63N, 40 links from, and facing, the remains of an old fence corner. Placed new monument, a 1"IOx32" iron pipe capped with a 4" dia. cast alseinum HDMR tablet, at record bearing and distance from the M. Pine and in the fance corner. Marked four new mitness trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (FS) found 1' pipe with 4' cap. (1) Found 1" pipe with 4" aluminum cap. (3) Set 1" pipe with 4" MOMR cap. Blazed and scribed the following new 10" spruce M29N 19.6" "1/165 BT" Blazed and scribed the following new 7" belsam \$500 11.7' '1/165 BT' bearing trees: bearing trees:

3" spruce \$19E 11.3" "1/45 HBT" 5' balsan \$45E 29.6' '1/165 81' 12" spruce \$018 36.6" "1/45 881" 12" spruce N15E 49.2' "1/165 AT" 4" spruce NOSE 54.4" "1/45 NBT" 4° belsam M82W 30.8' "1/45 NBT"

B" Codar N48W 37.6" "1/16S 81" 28" W. Pine N20N 32.0" 1/165 81" 3" Sugar 587# 8.8" "1/165 8T" 5" Sugar M82E 45.0" "1/165 B1"