

JAN 1 2 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 0 0 3 PAGE 0 3 3 3

17N 13W H-3 T R T R T R T R T R T R T R T R T R T	r corners in Lake	Located In:	Corner Code =##	R C ET L
1. Public Land Survey The State of Sta	(County)			
7	Public Land Survey			-1 3. O.C.
Froperty Controlling S T R R R Register of Deeds Stamp & File Number Property in Section S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R R Register of Deeds Stamp & File Number Property in Sec. S T R R R R R R R R R R R R R R R R R R				유
2. Property Controlling S T R R R Register of Deeds Stamp & File Number Property in Section S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Register Register of Deeds Stamp & File Number Register Re				유수 등 등
in Section S T R Property in Sec. S T R Property in Sec. S T R Register of Deeds Stamp & File Number Property in Sec. S T R Register of Deeds Stamp & File Number Property in Sec. S T R Register of Deeds Stamp & File Number	Description Controlling		· · · · · · · · · · · · · · · · · · ·	8 P 70 X0
3. Miscellaneous S T R Property in Sec. S T R Lot No. Recorded Plat 1. Lot No. Recorded Plat 2. Private Claims 3. Private Claims 4. Private Claims 5. Private Claims 6. Privat			`	8 1 2
Property in Sec. S T R Lot No. Recorded Plat Private Claims Robert L. Wetherell Robert L. Wetherell Robert L. Wetherell In a field survey on September 7, 95 Robert L. Wetherell September 7, 95 Robert L. Wetherell Robert L. Wetherell In a field survey on September 7, 95 Robert L. Wetherell Robert L. Wetherell Robert L. Wetherell In a field survey on September 7, 95 Robert L. Wetherell Robert Robert Robert L. Wetherell Robert L. Wetherell Robert L. Wetherell Robert Robert				· · · · · · · · · · · · · · · · · · ·
Robert L. Wetherelt in a field survey on September 7, 95 Iso hereby certify that under requirements of PA. 7.4. Michigan PA. C1970 (the corner points mentioned in the survey on September 7, 95 Iso hereby certify that under requirements of PA. 7.4. Michigan PA. C1970 (the corner points mentioned in the survey of the surve				
Robert L. Wetherell in a field survey on September 7, 95 In Chereby certify that under requirements of PA. 74. Michigan P. A. of 1970, the corner points meditioned intest 1 and 2 above with an conformance with the state of the corner points meditioned the corner points meditioned to the corner points meditioned to the corner points meditioned in the lighten by the corner points mentioned in the lighten by the corner of the corner points mentioned in the lighten by the corner of the corner of this certificate. Description of original mangrument and appearance points mentioned in the corner of the corner at the S.E. corn. of Plat. 1838 - Jehn Hodgson, G.L.O. 1839 - Jehn Hodgson, G.L.O. 1839 - Jehn Hodgson, G.L.O. 1850 - Market William of Plat. 1870 - George Blass, LS 5489 Found rotted cedar stake and irro carn the S.E. corn. of Plat. 1870 - Polic bast 16.36 1871 - Polic bast 16.36 1872 - Polic bast 16.36 1873 - Polic bast 16.36 1874 - Polic bast 16.36 1875 - Polic bast 16.36 1875 - Polic bast 16.30 187	Lot No, Rec	orded Plat		A B C D E F G H I J K
Robert L. Wetherett in a field survey on September 7, 95 In hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1. and 2 above were in conformance with regulations and rules therefore as required in the university of survey instructions of the University States Department of the Interior, Dureau of Land Anagament or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished, monumented, re-non-unersted, recovered, found as 3 bout of Law, established, re-astablished on this certificate. A. Description of original monument and accepssories, and of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats and recovered on the section of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats and recovered on the section of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats of Sections 3 bout of 1989 - Charles Rolnes, surveyor flats of the section of 1980 - Section flats flat				,
in a field survey on to necessary that survey on to necessary that under requirements of PA 74 Michianan PA of 1970, the corner points mentioned in the stand 2 above were in conformance with regulations and rules therefore as required in the times tand 2 above were in conformance with regulations and rules therefore as required in the times tand 2 above were in conformance with the rules of the Michianan Board or 100 Michianan Board Order Board or 100 Michianan Board Order Board or 100 Michianan Board Order Board Ord				
in a field survey on 19 Incretive entity haulands requirements of PA.7 Al, Michianan P. A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the times 1 and 2 above were in conformance with regulations and rules therefore as required in the times 1 and			Contember 7 95	4 7 8 9 10 11
nines 1 and 2 above were in conformance with regulations and rules therefore as required in the utrent manual of survey instructions of the United States Department of the Interior, Grueva of Land Anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 body were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law and/or that the corner points mentioned in lines 3, 4 and 5 body were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a surveyor of Law and for the rule of the Michigan Board of Land Surveyor or by a Corner of the Michigan Board of Land Surveyor or the Michigan Board of Land Surveyor or the Michigan Board of Land Surveyor of the Michigan Board of the Michigan Board of Land Surveyor (1836 – John Michigan Board of Land Surveyor) (1836 – John Michigan Board Mich	, i	n a field survey on		5
surrent manual of survey instructions of the United States Department of the Interior, Dureau of Land Amagement of the Valence of Count of Laws and of States of the Wichigan Board of Land Surveyors or by a Decree of a bown were in conformance with the rules of the Wichigan Board of Land Surveyors or by a Decree of a bown were in conformance with the rules of the Wichigan Board of Land Surveyors or by a Decree of a bown were in conformance with the rules of the Wichigan Board of Land Surveyors or by a Decree of a conformance with the rules of the Wichigan Board of Land Surveyors or by a Decree of a conformance with the rules of the Wichigan Board of Land Surveyors or by a Decree of a conformance with the rules of the Wichigan Board of Land Surveyor and the recorded on this certificate. Description of original monument and, accessories, and/or subsequent restoration: 1838 – John Neddagon, G.L.O. 1838 – Den Ledgagon, G.L.O. 1838 – Ohar Les Wolkings, Surveyor Platted "J.F. Gray's Addition "A" to Village of Baldwin Showed this corner at the S.E. cor. of Plat. 1940 – George Blass, LS 5689 Found rotted cedar stake and from cant hook 4'p below ground Level raised to surface with 1'p tipe. 1940 – George Blass, LS 5689 Found rotted cedar stake and from cant hook 4'p below ground Level raised to surface with 1'p tipe. 295 – P. Pole Vest 16.36' H – 8' Birch N. B.E. 76.50' H – 8' Birch N. B.E. 76.50' H – 9' Pole Vest 16.36' H – 9' Pole West 16.36' H – 1/4 corner common to Sections 3 and 10, 177H, R134. I found a 1/2" from rood 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several enouwents placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" from from found. The cooking is a province of the corner of the position of the origin	hereby certify that under requir	rements of P.A. 74, Michigan P.	A, of 1970, the corner points mentior	ned 6 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
Amagement of by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors of by a Decree of a 20ut of Law, established, monumented, re-monumented, recovered, found as 20ut of Law, established, re-established, monumented, re-monumented, recovered, found as 20ut of Law, established, re-established, monumented, re-monumented, recovered, found as 20ut of Law, established, re-established, monumented, re-monumented, recovered, found as 20ut of Law, established, re-established, monumented, re-monumented, recovered, found as 20ut 12, 12, 12, 12, 12, 12, 12, 12, 12, 12,	rrent manual of survey instruct	ons of the United States Department	artment of the Interior, Bureau of La	and 7
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories, and/or, subsequent restoration: 1838 - John Nedsson, 6.1.0. 1839 - John Nedsson, 6.1.0. 1830 - John Nedsson, 6.1.0. 1830 - John Nedsson, 6.1.0. 1831 - John Nedsson, 6.1.0. 1832 - John Nedsson, 6.1.0. 1833 - John Nedsson, 6.1.0. 1834 - John Nedsson, 6.1.0. 1835 - John Nedsson, 6.1.0. 1836 - John Nedsson, 6.1.0. 1837 - Platter "J. F. Gray's Addition "A" to Village of Baldwin. Showed this corner at the S.E. cor. of Plat. 1836 - P. Pole Rest 33.01 185 - P. Pole Rest 33.01 185 - P. Pole Rest 33.01 186 - P. Pole Rest 30.01 187 - P. Pole Rest 30.01 188 - P. Pole Rest 30.01 189 - P. Pol	inagement or by a decree of a C	ourl of Law and/or that the core	ner points mentioned in lines 3, 4 an	id 5 8 19 20 21 22 23
Note: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of orginal monument and accessories and 105 miles and 105	ove were in conformance with to our of Law: established, re-r	ne rules of the Michigan Board Established, monumented, re	e-monumented, recovered, found	as 9
on this certificate. Description of original monument and accessories and 100 11NN R139. 1838 — John Modigen, G.L.O. 1838 — Chartes Holees, Surveyor #1 — 8" Healock N37"£ 9 Links #2 — 4" B. Ash S5"U 7 Links **Corner at the S.E. cor. of Plat.** **Description of corner evidence found and/or method applied in restoring or regulablishing corner.** Description of corner evidence found and/or method applied in restoring or regulablishing corner.** 1940 — George Blass, LS 5489 Found rotted cedar stake and from cant hook 4 blook 9 blook ground Level raised to surface with 1" pipe. In 1966 re-uitnessed: 1940 — George Blass, LS 5489 Found rotted cedar stake and from cant hook 9 blook ground Level raised to surface with 1" pipe. In 1966 re-uitnessed: 1940 — George Blass, LS 5489 Found rotted cedar stake and from cant hook 9 blook produced the surface of Plat. 1960 — Recription of rotted cedar stake and from cant hook 9 blook produced to surface with 1" pipe. In 1966 re-uitnessed: 1940 — George Blass, LS 5489 Found rotted cedar stake and from cant hook 9 blook produced the surface of Plat. 1960 — Recription Plate 1960 ground Level raised to surface with 1" pipe. In 1966 re-uitnessed: 1954 — 8" Birch N.E. 76.50' #6 — N. end bridge abutments 163.2' #6 — N. end bridge abutments 1974. I did recover the C.1/4 corner and above, due to the re-construction of the bridge over the Baldvin creak in 1994. I did recover the C.1/4 corner and above, due to the re-construction of the bridge over the Baldvin creak in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldvin River and is 15' Vest of the centerline of highway h-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldvin River. Description of monument for corner and	pressed below:			10 30 29 28 27 26
Description of original monument and accessories and 10, 177N, R13W. Description of original monument and accessories established to perpetuate locating the position of the corner: 1838 - John Noctation, G.L.O. 181 - 8" Healock N37°E 9 Links 182 - 4" B. Ash 85°W 7 Links 182 - 4" B. Ash 85°W 7 Links 1838 - John Noctation, G.L.O. 181 - 8" Healock N37°E 9 Links 182 - 4" B. Ash 85°W 7 Links 1838 - John Noctation, G.L.O. 184 - 8" Birch N.E. 165.0" 185 - P. Pole East 38.01' 186 - P. Pole East 38.01' 186 - P. Pole East 38.01' 186 - P. Pole East 38.01' 187 - P. Pole East 38.01' 187 - P. Pole East 38.01' 188 - P. Pole East 38.01' 189 - P. Pole East 38.01' 180 - P. Pole East 38.01' 180 - P. Pole East 38.01' 181 - P. Pole East 38.01' 182 - P. Pole East 38.01' 183 - P. Pole East 38.01' 184 - P. Pole East 38.01' 185 - P. Pole East 38.01' 185 - P. Pole East 38.01' 186 - P. Pole East 38.01' 187 - P. Pole East 38.01' 188 - P. Pole East 38.01' 189 - P. Pole East 38.01' 189 - P. Pole East 38.01' 180 - P. Pole East 38.01' 180 - P. Pole East 38.01' 181 - P. Pole East 38.01' 181 - P. Pole East 38.01' 182 - P. Pole East 38.01' 183 - P. Pole East 38.01' 184 - P. Birch N.E. 76.50' 185 - P. Pole East 38.01' 185 - P. Pole East 38.01' 186 - P. N. end bridge abutments 163.2' 187 - P. Pole East 38.01' 188 - P. Pole East 38.01' 189 - P. Pole East 38.01' 189 - P. Pole East 38.01' 180 - P. Pole East 38.01' 180 - P. Pole East 38.01' 181 - P. Pole East 38.01' 181 - P. Pole East 38.01' 182 - P. Pole East 38.01' 183 - P. Pole East 38.01' 184 - P. Birch N.E. 76.50' 185 - P. Pole East 38.01' 185 - P. Pole East 38.01' 186 - P. N. end bridge abutments 163.2' 187 - P. Pole East 38.01' 188 - P. Pole East 38.01' 189 - P. Pole East 38.01' 189 - P. Pole East 38.01' 180 - P. N. end bridge abutments 163.2' 180 - P. N. end bridge abutments 163.2' 190 - P. Index of Pole Value and Pole Value and Pole Value and Pole Valu		iers, all in the same town	and range, may be recorded	
1838 - John Hodgson, G.L.O. 1818 - John Hodgson, G.L.O. 1818 - John Hodgson, G.L.O. 1819 - Strike Henlock N37 9 Links 182 - 4" B. Ash \$50 7 Links 1838 - Lant Henlock N37 9 Links 1839 - Charles Kolaes, Surveyor Platted "1,5". Gray's Addition "A" to village of Baldwin. Showed this corner 184 to village of Baldwin. Showed this corner 184 to village of Baldwin. Showed this corner 184 184 - 8" Birch N.E. 76.50 185 - P. Pole East 38.01 186 - N. end bridge abutments 163.2' 185 - N. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - P. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - N. Pole East 38.01 186 - N. end bridge abutments 163.2' 185 - N. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - P. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - P. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - P. Pole East 38.01 186 - N. end bridge abutments 163.2' 187 - P. Pole East 38.01 188 - P. Pole East 38.01 189 - P. Pole East 38.01 189 - P. Pole East 38.01 189 - P. Pole East 38.01 180 - N. end bridge abutments 163.2' 180 - N. end bridge abutments 163.2' 181 - P. Pole East 38.01 181 - P. Pole East 38.	on this certificate.			
1838 - John Hodgson, G.L.O. #1 - 8" Healock N37 E 9 Links #2 - 4" B. Ash 55" J 7 Links #2 - 4" B. Ash 55" J 7 Links #3 - 4" B. Ash 55" J 7 Links #4 - 4" B. Ash 55" J 7 Links #5 - 4" B. Ash 55" J 7 Links #6 - 4" B. Ash 55" J 7 Links #6 - 4" B. Ash 55" J 7 Links #7 - 4" B. Ash 55" J 7 Links #8 - 4" B. Ash 55" J 8 Links #8 - 4" B. Ash 55" J 8 Links #8 - 4" B. Ash 55" J 8 Links #8 - 4	Description of original mo	nument and accessories a	nd/or, subsequent restoration:	13 1
#1 - 8" Healock N37°E 9 Links #2 - 4" B. Ash \$5°U 7 Links Platted "1.F. Gray's Addition "A" hook 4' below ground level raised to surface with "pipe. In 1966 re-witnessed: #3 - P. Pole West 16.36' #4 - 8" Birch N.E. 76.50' #5 - P. Pole West 16.36' #6 - N. end bridge abutments 163.2' Bescription of corner evidence found and/or method applied in restoring or reestablishing corner: **CSEE_OVER FOR CONTINUATION OF "A" #3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' Vest of the centerline of Highway H-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. **Description of monument for corner and accessories established to perpetuate locating the position of the corner: #-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faith re-establishment of the position of the original corner. 10" W. Pine N66°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in N. side) 24" W. Oak S88°E 127.72' ((60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in N. side) 24" J. Of curve (1/2" iron in monument box) North 163.88'				1940 - George Blass, LS 5489
to Village of Baldwin. Showed this corner at the S.E. cor. of Plat. Nook 4' below ground level raised to surface with 1" pipe. In 1966 re-witnessed: #3 - P. Pole West 16.36' #6 - B' Birch N.E. 76.50' #5 - P. Pole East 38.01' #6 - N. end bridge abutments 163.2' Description of corner evidence found and/or method applied in restoring or reestablishing corner: 15' Cate over Por Continuation of "A" I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centertine of highway n-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13y. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithing re-establishment of the position of the original corner. 10" N. Pine N68°N 71.83' (60d spike in N. side) 24" N. Oak S88° 127.72' (60d spike in N. side) 24" N. Oak S88° 127.72' (60d spike in N. side) P. I. of curve (1/2" iron in monument box) North 163.88'		<u> </u>		
In 1966 re-witnessed: ##3 - P. Pole West 16.36' ##4 - 8# Birch N.E. 76.50' ##5 - P. Pole East 38.01' ##6 - N. end bridge abutments 163.2' BE OVER FOR CONTINUATION OF "A") B-3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the center-line of Highway N-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R134. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faith re-establishment of the position of the original corner. 10" W. Pine N68 ^{ON} 71.83' (60d spike in N. side) 24" W. Oak N88 ^{ON} 122.43' (60d spike in S. side) P. I. of curve (1/2" iron in monument box) North 163.88'		7 Links to Villa	age of Baldwin. Showed this	
#3 - P. Pole West 16.36' #4 - 8* Birch N.E. 76.50' #5 - P. Pole East 38.01' #6 - N. end bridge abutments 163.2' Bescription of corner evidence found and/or method applied in restoring or reestablishing corner: Continuation of Part Part Part -3 - 1/4 corner common to Sections 3 and 10, T17N, R134. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the center-line of Highway N-57. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R134. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithin re-establishment of the position of the original corner. 10" W. Pine N68 [©] W 71.83' (60d spike in N. side) 24" B. Oak N26 [©] W 122.43' (60d spike in S. side) P. I. of curve (1/2" iron in monument box) North 163.88'		corner a	at the S.E. cor. of Plat.	
#4 - 8" Birch N.E. 76.50' #5 - P. Pole East 38.01' #6 - N. end bridge abutments 163.2' B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. **Centerline N-37 East 15' **SEE OVER FOR CONTINUATION OF "A"** I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faith re-establishment of the position of the original corner. 10" N. Pine N68°N 71.83' (60d spike in N. side) 24" B. Oak N26°N 122.43' (60d spike in E. side) P.I. of curve (1/2" iron in monument box North 163.88')				
Description of corner evidence found and/or method applied in restoring or reestablishing corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N. -3 - 1/4 corner common to Sections 3 and 10, T17N, R13N, R13				•
Description of corner evidence found and/or method applied in restoring or reestablishing corner: Note: Corner common to Sections 3 and 10, T17N, R13N. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stared above, due to the re-construction of the bridge over the Baldwin creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway N-57. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R134. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" N. Pine N68°N 71.83' (60d spike in N. side) 24" N. Oak S88°E 127.72' (60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				
Description of corner evidence found and/or method applied in restoring of reestablishing corner: (SEE OVER FOR CONTINUATION OF "A") H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories staved above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithing re-establishment of the position of the original corner. 10" W. Pine N66°W 71.83' (60d spike in N. side) 24" W. Oak S88°E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				#6 - N. end bridge abutments 163.2
H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithin re-establishment of the position of the original corner. 10" W. Pine N68°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in N. side) 24" W. Oak S88°E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	Description of corner evid	ence found and/or method	d applied in restoring or reestab	olishing corner:
I found a 1/2" iron rod 12" below the surface of black top. I was not able to recover any of the accessories stated above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R134. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithfore-establishment of the position of the original corner. 10" W. Pine N68°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in E. side) 24" W. Oak S88°E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				
above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.1/4 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 71.83' (60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	H-3 - 1/4 corner common	to Sections 3 and 10, T17N	<u>, R13W.</u>	•
above, due to the re-construction of the bridge over the Baldwin Creek in 1994. I did recover the C.174 corner and several monuments placed by Surveyor Cole and Surveyor Blass that fit well with the 1/2" iron found. The corner is approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway M-37. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^O W 71.83' (60d spike in N. side) 24" B. Oak N26 ^O W 122.43' (60d spike in E. side) 24" W. Oak S88 ^O E 127.72' (60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	I found a 1/2" iro	n rod 12" below the surfac	e of black top. I was not abl	e to recover any of the accessories stated
approximately 170' North of the Baldwin River and is 15' West of the centerline of Highway N-3/. There is approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	shove due to the	re-construction of the bri	dge over the Baldwin Creek in	1994. I did recover the C.1/4 corner and
approximately 10' of fill in this area for the approach to the bridge over the Baldwin River. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13H. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithfure-establishment of the position of the original corner. 10" W. Pine N68°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in E. side) 24" W. Oak S88°E 127.72' ((60d spike in S. side) P. I. of curve (1/2" iron in monument box) North 163.88'	several monuments	placed by Surveyor Cole an	d Surveyor Blass that fit Well	with the 1/2" from found. The conner is
Description of monument for corner and accessories established to perpetuate locating the position of the corner: H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P. I. of curve (1/2" iron in monument box) North 163.88'	approximately 170'	North of the Baldwin Rive	he annroach to the bridge over	the Baldwin River.
H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	approximately 10.	of fill in this area for t	the approach to the prinage over	,
H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^O W 71.83' (60d spike in N. side) 24" B. Oak N26 ^O W 122.43' (60d spike in E. side) 24" W. Oak S88 ^O E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				: :
H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^O W 71.83' (60d spike in N. side) 24" B. Oak N26 ^O W 122.43' (60d spike in E. side) 24" W. Oak S88 ^O E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				
H-3 - 1/4 corner common to Sections 3 and 10, T17N, R13W. I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				
I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	Description of monument	for corner and accessorie	s established to perpetuate loc	ating the position of the corner:
I replaced the 1/2" rod with a 3/4" x 24" re-bar with Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner. 10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	H-3 - 1/4 corner common	to Sections 3 and 10, T17h	v, <u>r13W.</u>	
re-establishment of the position of the original corner. 10" W. Pine N68°W 71.83' (60d spike in N. side) 24" B. Oak N26°W 122.43' (60d spike in E. side) 24" W. Oak S88°E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				and is accounted as a careful and faithful
10" W. Pine N68 ^o W 71.83' (60d spike in N. side) 24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	I replaced the 1/2	" rod with a 3/4" x 24" re	e-bar with Lake County Brass Ca	ip, and is accepted as a careful and farming
24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'	re-establishment o	if the position of the orig	gmac comer.	The state of the s
24" B. Oak N26 ^o W 122.43' (60d spike in E. side) 24" W. Oak S88 ^o E 127.72' ((60d spike in S. side) P.I. of curve (1/2" iron in monument box) North 163.88'				ALE TATE OF MONEY
P.I. of curve (1/2" iron in monument box) North 163.88'	24" B. Oak N26 ⁰ W 1	122.43! (60d spike in E. s	ide)	1 Pont m
P.I. of curve (1/2" iron in monument box) North 163.88				I I ver mer
Guard rail post NOV E 24.31 (r.n. nail in top)	P.I. of curve (1/2	iron in monument box) No	ortn Top.öö' ton)	3 - 1 50
Y A P P P P P P P P P P P P P P P P P P	Guard rail post N	D / P.K. Nait in '	ιορ/	FOX SEC STORY
(fout 1 Wetherell Date 10-26-95, 0, 24,24	Lebert	I. Wethe	rello Date	10 -26-95, 0 24-24
Signed by	gried by			TO THE OWN
Surveyor's Michigan License No	ırveyor's Michigan License	NO. DATIFIED BY THE LAKE C	O PEER REVIEW GROUP	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND CONVEYORS.

CONTINUATION OF "A" - DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

1946 - George Blass, L.S. 5489

Survey dated August 16, 1946: Surveyed a parcel of land beginning 745' South and 620' West of this corner. Map on File at the office of Wetherell Land Surveying.

LIBEROO3 PAGEO334

1957 - George Blass, L.S. 5489

Surveyed several parcels in the E.1/2 of N.W.1/4, Sec. 10. Blass Survey File No. 453 on file at the office of Wetherell Land Surveying.

SURVEY & FEMONUMENTATION

1971 - George Blass, L.S. 5489

Survey recorded in Liber 1, Page 42

#3 - P. Pole N85°W 16.351

#6 - Guard Rail Post \$10°W 74.65'

#7 - N.W. corner bridge abutment S.W. 145.91'

COMMISSION

JAN 1 2 1996

1972 - Clinton Cole, L.S. 17615

1" Pipe (Survey recorded in Liber 1, Page 40)

#3 - P. Pole West 16.361

#4 - 8" Birch N.E. 76.50"

#5 - P. Pole East 38.01