

SURVEY & REMONUMENTATION

AUG 15 2005

REC'D AUG 9 2005

2004 Newaygo County Remonumentation Project

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Newaygo
(County)

Located in: Corner Code #

VOL. 4 338

- 1. Public Land Survey
T14N R11W
T N R W
T N R W
T N R W
T N R W
T N R W
T N R W
- 2. Property Controlling
in Section
S
- 3. Miscellaneous
Property in Sec.
S



LINDA M. LANDHEER
NEWAYGO COUNTY REGISTER OF DEEDS
RECEIVED & RECORDED
08/09/2005 11:35:59 AM

Register of Deeds Stamp & File Number

- 4. Lot No. _____ Recorded Plat _____
- 5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Norman L. Ochs, in a field survey on January 05, 2005, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 2, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Note: Not more than 2 corners, all in the same town and range, may be Recorded on this certificate.

Section corner common to Sections 29, 30, 31 and 32, Goodwell Township, Newaygo County.

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

GLO - J. H. Mullett
1837
Set post corner
#1 30" Hemlock S71°E 29 links (19.14')
#2 12" Hemlock N41°E 34 links (22.44')

Delos Anderson - County Surveyor
Book A, Page 216 September 4, 1897
#3 6" Hemlock SW 1 links (.66')

OVER

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

I found a 1" x 16" iron Pipe with a 1/2" x 20" re-rod pounded in center. The corner is 3' South of centerline of East-West gravel road. The corner is 3' East of centerline of gravel road to South. The condition of the witnesses are as follows: #1 thru #4 are gone, #5 thru #7 are in good condition, #8 found stump uprooted N55°E 46' center hole.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

I removed the 1/2" x 16" iron pipe and 1/2" x 20" re-rod and set a 4" diameter Harrison cast iron monument 20" long marked "County Surveyor #22439" at ± .5' below grade as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the position of the original section corner.

- #5 Power Pole S45°W 47.75'
- #6 20" Maple N72°W 93.70'
- #7 10"-6" Twin Maple S41°E 37.04'
- 10" Black Oak N78°E 97.88'

- Reset 40d spike with tag in SE side
- Found spike in North side
- Found spike in NE side
- Set spike with tag in South side

Signed by Norman L. Ochs
Norman L. Ochs

Date July 20, 2005

Surveyor's Michigan License No. 22439

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1975
Revised Jan., 1983

Approved by Peer Review Group on April 28, 2005
Norman L. Ochs, County Representative.

