



**FIELD REVIEW NOTES FOR GNA-Ottawa-FY23-Project#3 [5/14/2024]**

C-S 1/16th Corner S18

- NE & SW BT's Checked
- added over spray
- some runoff paint and flaking
- markings and posts visible East & South
- Monument Cap cracked
- Cut tree in SW Quad (on private)

C-S 1/16th Corner S18 -> SOUTH

- Some brush piled on Private Lands
- Rails not placed at tops and toes; appear to be placed at a set interval
- witness markings over 3 feet from line in areas, makes line appear to bow or wiggle as a result
- Positive; good number of line trees found on this line

N 1/4 Corner S 19

- NW & NE NBT's Checked
- Corners weren't repainted by contractor
- No etching / stamping on signs

N 1/4 Corner S 19 -> South

- Added one line tree
- Brush on Private
- Existing Blue Line +/-10 feet West of line near the North end of the Lake
- repainted several witnesses; paint ran off

C ¼ S19

- NW NBT's Checked
- Drove down High post
- Line Post visible North & West

(MOVE to West Side of Lake) E-W ¼ line S19 -> West

- Some hanging limbs
- Line Tree not chopped through the cambium layer; re-chopped and repainted said line tree
- Existing Blue Line / ribbon line +/- 12 feet South of line

C-W 1/16th Corner S 19

- NE & SE BT's Checked
- some brush online between corner and witnesses
- post visible East, not North.... Tree on line to the North

C-W 1/16th Corner S 19 -> North

- good number of markings in this segment
- good number of line trees marked in this segment
- Freshened up paint on several blazes

  
SIGNATURE

MICHIGAN DNR Land Survey Manager  
TITLE

## FS-6300-21

W 1/16th Corner S18 | 19

- East & SW (Yellow) BT's checked
- Creek/drainage visible near corner, is it called for on GLO notes (check)

W 1/16th Corner S18 | 19 -> North

- less markings in this segment but they are closer to line, so it presents a straighter line
- some brush on private
- some remnants of an old fence line are visible in this segment

C-W 1/16th Corner S18

- NE & SW BT's checked

C-W 1/16th Corner S18 -> North

- cleared to the North to the river
- line marking visible on the other side of the river

MOVE to C-N 1/16th Corner S18

- NE & SW BT's checked
- Maple BT's available NW (Poplar used in this quadrant)
- Repainted all witnesses

C-N 1/16th Corner S18 -> East

- Some brush of Private
- Creek visible, no adjacent post & not on map
- OK for # of markings

N 1/16th Corner S18

- Found Drill Rod and 4 signs

### GENERAL COMMENTS:

OK on number of marks. Cutting and clearing appears to be well done. A good number of reference marks and a fair number of line trees. Some areas for improvement (as simple as repainting the existing witnesses or replacing a broken cap or making more of a conscious effort to move ALL of the brush to USFS lands) but overall it was acceptable work.

  
SIGNATURE

MICHIGAN DNR Land Survey Manager  
TITLE