1995 Alcona County Remonumentation Corner

Alcona County Remonumentation Liber_

LAND	CORNER	RECO	RDATIO	N CE	RTIF	ICATI
Cilina	Requirem	ant of	A c+ 74	Mich	DΔ	1070

г.	ara ira	Filing Red	quirement of Act 74, Mich. P.A. 1970 RECORDED
ro	r corners in Alcona (County)	Located In:	Comer Code #
1.	Public Land Survey	T <u>25N</u> _ R <u>{</u> T R _ T R _ T R _	Jane a Buchen
2.	Property Controlling in Section	S T R _ S T R _	788 V
3.	Miscellaneous	S T R_	Begister of Deeds Stamp & File Number
	Property in Section	STR_	
		, Recorded Plat	
			2 - 6 5 3 2 1 - 1
	-		3 4 7 8 9 10 11 12
do in l ma Ma	hereby certify that under ines 1 and 2 above were anual of survey instruction	requirements of P.A. 74, Michig in conformance with regulations tions of the United States De e of a Court of Law and/or that t	June 2 , 19 95 , an P.A. of 1970, the corner points mentioned and rules therefore as required in the current partment of the Interior, Bureau of Land he corner points mentioned in lines 3, 4 and an Board of Professional Surveyors or by a

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found

1838: G.L.O. Survey by Lewis Clason - Set post and referenced Elm 10 - S60W - 32 / B.Alder 3 - N30W - 13

1928: Dependent Resurvey by Guy R. Veal - Set Iron post 3 ft. long, 2 ins. in dia. with brass cap.

1967: Survey by R.S. Scott Eng. Co. - Found 1927 Gov't Cor.

1986: Survey by Ledy Eng. and Sur. - Found Iron post 2" dia. with brass cap under surface of Beaver Pond.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1995: Found 2" Iron Pipe with brass cap in old Beaver flooding.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1995: 2" Iron Pipe with brass cap stamped to identify the corner.

Referenced: North - 1/2" Iron Rod - 141.15 Feet

West - 1/2" Iron Rod - 87.11 Feet

North - 20" Oak - 99.30 Feet S05°W - 1/2" Iron Rod - 41.95 Feet

/ An State Board of Professional Surveyors, Jan. 28, 1971 Revised May 14, 1975 Revised Jan., 1983

UB. low

Surveyor's Michigan License No.___

as expressed below:

on this certificate.

22435

DAVID B ND SULVEYO