Approved by Alger Cour Land Survey Remonument Peer Group Under Act 34 P.A. of 1990 On <u>5/8</u> 10	12000 15 of 13 96 1502	,		2	<u> </u>	38	9		
Chairman For corners in Alger (County)		ent of Act 74, Mich. P.A Corner Code #			•	ILED		<i>7</i>)	<u>-'</u>
Public Land Survey	T <u>46N</u> R <u>18W</u> T <u>46</u> R <u>17</u> T <u>R</u>	M10 (A 10)		JUN 27 1996 DONALD W. KINNUNEN REGISTER OF DEEDS					
 Property Controlling in Section Miscellaneous Property in Section 	S T R S T R S T R S T R		Registe		ds Stam			mbe	:r
4. Lot No, 5. Private Claims,	Recorded Plat			A B C	D E	F G	H		K L
do hereby certify that under re in lines 1 and 2 above were in manual of survey instruction Management or by a decree of 5 above were in conformance	, in a field survey on Februsequirements of P.A. 74, Michigan P.A. of conformance with regulations and rule as of the United States Department of a Court of Law and/or that the come with the rules of the Michigan Board (ablished, re-established, monumented)	of 1970, the corner points ment is therefore as required in the co it of the Interior, Bureau of it points mentioned in lines 3, it of Professional Surveyors of	tioned a urrent Land 4 4 and 8 r by a	3 — 18 — 7 — — 3 — — 19 — — 9	-17	21	15	-14	13-

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

as expressed below:

M10: PLS-William A. Burt, DS, 1841, Set gr. section post - Birch 14°, S.51 E., 33 links, Birch 30°, N.22 W., 29 links. No subsequent restoration.***** Alger county Road Commission, 1986-1989, Robert L. Jamros, PS, established corner position at single proportionate mesurement between existing corners North and South for road alignment purposes prior to the reconstruction and paving of Percy Road.***** Pete Beaver, PS, 1995, State of Michigan Department of Management and Budget. Verified corner position by survey work for the Department of Corrections. No references made.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M10: Found 1/2° Rebar with cap no. 25849, 1.2 feet East of the centerline of Percy Road, 6° deep. Corner position verified as being established on line and at single proportionate distance between BT Section corner of Sections 13, 24, 18, and 19, T.46N., R.17-18W., and BT Section corner of Sections 25, 36, 30, and 31, T.46N., R.17-18W. Corner position lies in open graded area around the Cusino Correctional Facility and all evidence of original BT's has been destroyed. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

SURVEY & REMONUMENTATION

JUL 3 0 1996

COMMISSION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M10: Set 5/8"x 18" rebar with Berntsen 3 1/4" aluminum cap no. RBD5325, stamped to identify corner position, along side existing 1/2" rebar, grouted in place with concrete. Established the following references. ** Six foot steel fence post w/ survey marker sign, S.54 E., 43.02 feet, ** Six foot steel fence post w/ survey marker sign, N.50 E., 53.08 feet, ** Six foot steel fence post w/ survey marker sign, N.24 W., 90.29 feet, ** Pole, Electrical Transmission line, S.81 W., 37.60 feet, Scribed BI at base of pole. A PK nail w/ aluminum I.D. washer on side of pole for measure. All bearings are magnetic.

Signed by Aut James
Surveyor's Michigan License No. 25849

SURVEYOR
No.
Date /Z 25849

FORM APPROVED BY MICHIGANS (A FEBOLAD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

ROBERT L. JAMROS PROFESSIONAL

> REVISED MAY 14, 1975 REVISED JAN., 1983