REMONUMENTATION

FEB 1 9 1998

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 348 c

SECTION

05-61

P.A. of 1990 On 17-10 1397 Geraldia Co LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Act 74, Wilch, F.A. 1970		
For corners in	Located In:	Corner Code #	i F.LED
(County) 1. Public Land Survey	46 17 T = 8 = 172 T = R = R		DEC 17 1997
 Property Controlling in Section Miscellaneous Property in Section 	T R S T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY. MI Register of Deeds Stamp & File Number
4. Lot No 5. Private Claims	, Recorded Plat		2 6 5 4 3 2 1 1 1 12 12
do hereby certify that under in lines 1 and 2 above were in manual of survey instruction Management or by a decree 5 above were in conforman Decree of a Court of Law; eas expressed below:	, in a field survey on requirements of P.A. 74, Michigan P.A. n conformance with regulations and mons of the United States Department of a Court of Law and/or that the conce with the rules of the Michigan Bostablished, re-established, monument corners, all in the same town and the	A. of 1970, the comer points menules therefore as required in the client of the Interior, Bureau of the Professional Surveyors of the covered, recovered, recovered,	tioned 6 18 17 15 14 13 15 14 13 15 14 13 15 14 15 15 14 15 15 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15

Description of original monument and accessories and/or subsequent restoration:

C8: PLS - William Ives, D3: 1950 * Set quarter section post * Beech 8, 5.32 E., 29 links * Sugar 8, N.8.2 W., D2 links ****** George L. Depew, County Surveyor, 1917 * Set standard iron corner, 1 BT found * No references ***** Munising-Shingleton Foad, corner is shown (no detail) on construction plans, M.D.S.H., 1958 ***** Land Corner Record * Michigan Department of Conservation * Silly D. Buckler, 1960 * Corner position in monument cox 4 3/4 links West of centerline of M-94 and in line with fence to West * No references given * Recorded in Liber 2, Page 193, Alger County Corner Records ***** No other subsequent restoration.

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

CB: Found 1 inch iron bar in monument box, 3.3 feet West of the centerline of pavement of County Road H-15 (old M-94) * Old fence line evident to West from corner * Corner position measures well to corners North, South and West * Monument box position has been maintained and corner position has been accepted and used in area surveys. * Monument box and corner position are accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

CB: Replaced 1 inch ican par 4/5/8 inch by 18 inch Rebar w/Berntsen Alum, cap no. RBD 5325 in exist, monument Edx, 3.3 feet West of centerline of pavement of County Road H-15 * Established reference trees W/8T signs, blazed and scribed * Set Ph halls W/Alum. I.D. washers for measure in the following - Maple 9, S.33 E., 56.42 feet, 'BT' * Maple 7, S.67 W., 34.68 feet, 'BT' * Spruce 7, N.44 E., 32.78 feet, "BY" * White Eiron 5, N.23 W., 53.61 feet, no scribing or BT signs * All bearings are magnetic.

Signed by Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSK

RODERT JAMROS PROFESSICILA

REVISED MAY 14, 1975