## SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 48 1995

expressed below:

on this certificate.

MAY 1 0 1995

10

12

## Herole Commission LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich. RA 1970

4-285

Chairman For corners in	Filing Require	ement of Act 74, Mich. P	P.A. 1970
Alger	Located In:	Corner Code ##	MLED
(County)			SE 9:00 am.
Public Land Survey	T4\$\text{K}_R1\text{\$\text{K}_\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		APR 20 1995
2. Property Controlling	S T R		REGISTER OF STREET
in Section	\$ T R		
Miscellaneous     Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		ABCDEFGHIJKL
5. Private Claims			2 - 6 - 5 - 4 - 3 - 2 - 1 -
			3 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
	, in a field survey on		inned       henni
in lines 1 and 2 above were	e in conformance with regulations an structions of the United States Depar	nd rules therefore as required	in the 6 18 17 16 15 14 13
	of a Court of Law and/or that the corne		

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

C2: PLS-George E. Adair, DS, 1855, Set Qr. Section Post- Spruce 7", N.27 W., 20 links, Tamarack 12", S.56 1/2 E., 30 links. CCI Forestry Division, Land and Timber Examination Report. R.J. Brotherton, RLS, and J.R. Radcliffe, RLS, indicate corner as post, 4" Sq. Spruce and down Tamarack GLO BT, 1943 through present.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C2: Began at corner of Sections 5 and 6, T.46N., R.18W. and Sections 31 and 32, T.47N., R.18W., Ran corrected compass line on GLO bearing south. At 7.2 ch. (GLO 7.17 ch.) found remains of M.Pine stump, 42" estim. (GLO 28"). At 31.92 ch. (GLO 31.87 ch.) found M.Pine stump, 32" estim. (GLO 14") on top of knob, GLO combined call. Found are pointed post point at 40.45 ch., GLO 40.37 ch., remains of post have decayed beyond recovery. From post point location of 40.45 ch. located stump remains of Tamarack in the GLO BT location of 5.56 1/2 E., 30 links. Tamarack log is down and badly decayed. Replaced post point with nonument and established reference trees. Corner lies in thick, wet Spruce marsh. Found old blaze line running north from corner position. Corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C2: Set 2 1/4" Alum. Honument for corner and accessories established to perpetuate locating the position of the corner:

C2: Set 2 1/4" Alum. Honument w/ 3 1/4" Alum. Cap stamped to identify corner position. Established reference trees w/ BT Signs, blazed, scribed and painted. Set PK nails for measure w/ brass I.B. washers in the following reference trees. W.Pine 20", N.69 W., 22.90 feet, "1/4s BT", W.Pine 10", N.22 E., 20.88 feet, "1/4s BT", Maple 10", S.33 E., 33.74 feet, "1/4s BT", W.Pine 22", S.42 W., 65.07 feet, "1/4s BT", Steel witness post with Survey marker sign, N.42 W., 2.0 feet, All bearings are magnetic.

_		
Signed by	tabut the annas Date	12 April, 1995
Surveyor's Michigan License	1	
Surveyor's Michigan License in	0	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975