Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-12-19 95

Seralda Carlson Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JAN 2 3 1996

COMMISSION 4 - 330

For corners in	Located In:	Corner Code #	7-550
Alger (County)	Localed In.	Comer Code #	REC'D and FILED
Public Land Survey	T <u>46N</u> R18W T <u>47N</u> R1 <u>8W</u> T R T R	_	DEC 20 1095 2145 p.m. DOWNED VICTORIANTE County Clerk
Property Controlling in Section	S T R S T R		ALMER COUNTY, MI
3. Miscellaneous	S T R		
Property in Section	S T R		Register of Deeds Stamp & File Number
4. Lot No, (Recorded Plat		A B C D E F G H I J K L
•			3
			4 7 8 10 10 11 11 12
I, Robert L. Jamros	, in a field survey onAu	gust 31, 1995 , 19	, 5
do hereby certify that under re	quirements of P.A. 74, Michigan P	A. of 1970, the comer points mer	ntioned 6 18 17 16 15 14 13
		rules therefore as required in the ment of the Interior, Bureau of	
		corner points mentioned in lines 3	
		Board of Professional Surveyors	
	ablished, re-established, monume	nted, re-monumented, recovered,	, found 10 30 29 28 27 26 25
as expressed below:			
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11
			13

A. Description of original monument and accessories and/or subsequent restoration:

H1: PLS-William A. Burt, DS, 1841, Set Qr. Section Post- Sugar 18", N.39 E., 22 links, Sugar 6", N.37 W., 37 links. Walter W. Gleason, County Surveyor, 1913, Set standard iron corner on straight line and halfway between section corners. No references given. Record book of surveys, page 122. Alger County Records. Corner position shown on MDSH Project plans No. 02022 and 2-28 for highway M-94. Monument material and witnesses not given. CCI Forestry Division, Land and Timber Examination Report, R. Radcliffe, RLS, 1950, Notes on timber cruise sheet iron corner at corner postion. No references given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H1: Found 2 1/4 inch galvinized iron pipe with 3 1/4 inch brass cap, no markings, north of east-west paved road and 2 1/4 inch galvinized iron pipe w/ slanted brass plate marked " 33 feet N. to 1/4s ", south of east-west paved road, author unknown. Measurements between monuments is 66.22 feet. Established corner position on line between monuments and 33 feet north of monument with slanted plate. Measurements to corners east and west along highway compare to highway records very well. A search was made with a locator for a iron monument under highway with no results. A search was made at GLO bearing tree positions, evidence is lost. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

HI: Set 5/8" x 18" rebar w/ Berntsen Cap no. RBD5325 stamped to identify corner position. Established the following reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Maple 8", N.51 E., 46.58 feet, " 1/4s BT ", Twin Maple 6" & 8", N.37 W., 64.95 feet, " 1/4s BT ", Spruce 7", S.27 W., 45.98 feet, " 1/4s BT ", Maple 5", S.22 E., 57.36 feet, " 1/4s BT ". All bearings are magnetic.

ATE

Signed by Talut & Emiss

Surveyor's Michigan License No.

Z5849

ROBERT L.

JAMROS

LAND SURVEYOR

NO

SPED LAND

OF MICHIC

NO December

1995

DOVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983