Approved by Alger County Land Survey Flamonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-12-19

iroldwart Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JAN 2 3 1996

COMMISSION

For corners in			4-332
Alger (County)	Located In:	Corner Code #	7-008
Public Land Survey	T <u>46N</u> R <u>18U</u> T <u>47N</u> R <u>18U</u>		REC'D and FILED
 Property Controlling in Section Miscellaneous Property in Section 	T R T R S T R S T R S T R		DONALD WARRENDSH County Clerk ALGER COUNTY, MI Register of Deeds Stamp & File Number
4. Lot No	Recorded Plat		A B C D E F G H K L 2 6 5 4 3 2 10 11 12
do hereby certify that under re- in lines 1 and 2 above were in manual of survey instruction Management or by a decree of 5 above were in conformance	equirements of P.A. 74, Michigan conformance with regulations and so of the United States Depart of a Court of Law and/or that the with the rules of the Michigan	P.A. of 1970, the corner points ment d rules therefore as required in the c rtment of the Interior, Bureau of corner points mentioned in lines 3, Board of Professional Surveyors of tented, re-monumented, recovered,	ntioned 6 18 17 16 15 14 13 to the first of
NOTE: Not more than 4 con this certificate.	orners, all in the same town a	nd range, may be recorded	12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

J1: PLS-William A. Burt, DS, 1841, Sugar 5" qr.section corner - Sugar 12", N.33 W., 36 links. Alger County Road Commission survey note books, Walter W. Gleason, County Surveyor, 1913, Set standard iron corner from original government field notes. No references given. Volume 1, page 50 and 51. Corner position shown on HDSH Project plans No. 02022 and 2-28 for highway M-94. Monument material and witnesses not given. CCI Forestry Division, Land and Timber Examination Report, R. Radcliffe, RLS, 1950, Notes on timber cruise map an iron corner at corner postion. No references given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J1: Found 2 inch galvinized iron pipe with 3 1/4 inch brass cap marked " 1/4s 33 feet south", Author unknown, north of east-west paved highway. A search was made with locator for a iron monument under highway with no results. Established corner position 33 feet south of brass capped monument. Measurements to corners east and west along highway compare to highway records very well. A search was also made at 610 bearing tree positions, evidence is lost. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J1: Set 5/8" x 18" rebar w/ Berntsen Cap no. RBD5325 stamped to identify corner position. Established the following reference trees w/ BT signs, blazed, scribed and painted. Set PK mails for measure #/ Alum. I.D. washers in the following reference trees. Maple 10°, N.36 W., 54.00 feet, " 1/4s BT ", Maple 5", N.28 E., 49.48 feet, " 1/4s BT ", Two inch G.I.P. w/ brass cap, N.04 E., 33.0 feet, " Wit. Mon. ', Maple 8', \$.52 E., 80.86 feet, * 1/4s BT ". All bearings are magnetic.

25849 Surveyor's Michigan License No.

ROBERT L **JAMROS** LAND SURVEYOR _NDate

PED LAND

25° FORM APPROVED BY INCHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1963