SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Flornonumentation Peer Group Under Act 345 of P.A. of 1990 On 5/8

5. Private Claims _

JUL 3 0 1995

COMMISSION LAND CORNER RECORDATION CERTIFICATE

4:388

elul Chairman For corners in Filing Requirement of Act 74, Mich. P.A. 1970 Corner Code # Alger Located in: **FILED** TIME _3:00pm 1. Public Land Survey T 46N R 18W JUN 27 1996 R T 46 R 17 ____ R ____ DONALD W. KINNUNEN т REGISTER OF DEEDS 2. Property Controlling Ŧ _ R ALGER COUNTY, MI in Section Т __ R _ R 3. Miscellaneous Т Register of Deeds Stamp & File Number Property in Section ___, Recorded Plat_ Lot No.

Robert L. Jamros	_ , in a field survey on	February 08, 1996	, 19,
do hereby certify that under re	equirements of P.A. 74, Mich	igan P.A. of 1970, the cor	ner points mentioned
n lines 1 and 2 above were in	conformance with regulation	ns and rules therefore as r	equired in the current
manual of survey instructio		•	•
Management or by a decree		•	•
5 above were in conformanc		•	, ,
Decree of a Court of Law; es	tablished, re-established, me	onumented, re-monument	ed, recovered, found
se avaracead halawr			

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M9: PLS-William A. Burt, OS, 1841, Set post corner of sections 24 & 25 - Cedar 14', N.66 W., 38 links, Birch 20', S.64 E., 21 links.***** George L. Depew, CS, 1917, Set iron corner from Government Field notes. No references given. No sebsequent restoration.***** Alger County Road Commission, 1986-1989, Robert L. Jamros, PS, established corner position at single proportionate measurement between existing corners North and South for road alignment purposes prior to the reconstruction and paving of Percy Road.***** Pete Beaver, PS.1995, State of Michigan Department of Management and Budget, Verified corner position by survey work for the Department of Corrections. No references made.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M9: Brass capped corner monument of 1917 has been lost and this is supported by testimony of local residents. Found 1/2' Rebar with I.D. cap no. 25849, 5.6 feet East of the centerline of Percy Road, 8' deep. Corner position verified as being established on line and at single proportionate distance between BT Section corner of Sections 13, 24, 18, and 19, T.46N., R.17-18W., and BT Section corner of Sections 25, 36, 30, and 31, 7.46N., R.17-18W. Stream to the North checks very well with GLO Survey call of 1.25 chains. Stream 12 links, C. E., Corner position lies in grade separation of Percy Road approach to Hickey Creek to the North and all evidence of original BI's has been destroyed. Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M9: Set 5/8"x 18" rebar with Berntsen 3 1/4" aluminum cap no. RBD5325, stamped to identify corner position, along side existing 1/2" rebar, grouted in place with concrete. Established the following references. Reference trees have BT signs and are blazed, scribed and painted. Set PK mails for measure w/ aluminum I.D. washers in the following reference trees; Cherry 13", S.68 E., 29.84 feet, "\$30 87". ** W. Pine 24", S.71 W., 48.61 feet. "S25 BT". ** Six foot steel fence post w/ survey marker sign, N.45 W., 47.08 feet.** Six foot steel fence post w/ survey marker sign, N.64 E., 39.68 feet. All bearings are magnetic.

Signed by_

Surveyor's Michigan License No.

Date

PROFESSIONAL SURVEYOR No. 23849

OF MIC

ROBERT L **JAMROS**

M STATE HOARD OF HE FORM APPROVED BY MICHIG NAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983