Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On 7 7 19
P.A. of 1990 Qn 2/7 19 27
My Davi

Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

4-266

For	corr	nare	in

expressed below:

Located in: Corner Code ## Public Land Survey T __47N R _22N_ T _____ R ___

ые <u>2:35 р.м.</u>

NOV 17 1994

0	Secretary Control William		_ R		l	REGISTER OF DEEDS									
2.		S T													
_	in Section	S T	_	***											
Miscellaneous	Miscellaneous	S T	_ R			Registe	er of I	Deeds	Stan	np &	File	Nur	nbei	r	
	Property in Sec.	S T	_ R												
	I at Ma	December 4 Dist													
	Lot No,				····-		А В	C	E 1	F G	н	1 1	к	Ł	M
5.	Private Claims						\Box	T			\top			Т	_
						2	├- <u>-</u> 6-	┼		-	ġ	+-:	2-1	į -	_
						3	$\vdash \vdash$	+				4		-	
						4	L !	1			_ _10_	Т.	<u> </u>	_ —12	
1	Robert L. Jamros	. in a field survey o	on Asion	ist 14. 1993	19	. 5		li			Ĩ			Ī	
	hereby certify that under re									Т	\top			T	
in I	ines 1 and 2 above were	in conformance with r	regulations an	d rules therefo	re as required in th	ne 6	18-	 1 7	1-1	•	15	1-1	4	13- I	_
cur	rent manual of survey inst	ructions of the United	States Depart	lment of the Int	erior, Bureau of Lan	id 7	┡╼┿┈	++		-	+	╀	$\vdash \vdash$	-+	
Ма	nagement or by a decree of	fa Court of Law and/or	that the corne	r points mentio	ned in lines 3, 4 and	5 g	 19	1-20		1	22		3	_2 4	
abo	ove were in conformance w	ith the rules of the Mic	higan Board o	of Land Surveyo	rs or by a Decree of	a o	Ιï	Ιĩ	آ ا		Ĩ		ĭ	Ī	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Court of Law; established, re-established, monumented, re-monumented, recovered, found as

A. Description of original monument and accessories and/or subsequent restoration:

D5: P.L.S., Alfred Hillard, DS, 1852. Set quarter section post. Maple 12, S.52 E., 38 links. Hemlock 10, N.70 W., 53 links. No subsequent resoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D5: Ran corrected compass line on G.L.O. Bearing east from section corner 7, 8, 17 & 18, to 40.0 chains. A search was made at original BT locations for remaining evidence of Maple and Hemlock. At N.70 W., 50 links found remains of Hemlock roots in stumphole. At 5.52 E., 38 links found 24° Maple w/blaze scars, an original BT alive and standing. From Maple estab. corner position in small swamp hole and found 14' long are pointed post point. Installed monument at post point location and estab. new reference trees. Section corner to west 40.0 chains supports this corner position and is accepted as a careful and faithful perpetuation of the position of the original corner.

C. D5. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Alum. cap stamped to I.D. corner. Est. reference trees w/BT signs, blazed, scribed and painted. Set PK nails for measuring w/brass I.D. washers in the following reference trees. Y. Birch 12", N.30 H., 45.63 feet, "1/4S-BT". Cedar 14", N.74 E., 33.83 feet, "1/45-81". Hemlock 14", \$.42 E., 33.10 feet, "1/45-BT". Black Ash 6", S.64_W., 61.68 feet, Not Scrd. Survey Marker Sign, South 1.0 feet.

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983