| Approved by Alger County |
|--------------------------------|
| Land Brayov Roy Research Colon |
| Peer @load childer Act 645 01 |
| P.A. of 1220 Ch 4-8 1995 |
| Shall W Carlson |
| Character |

LAND CORNER RECORDATION CERTIFICATE

205

REVISED JAN., 1983

| Chairman - | Filing Requ | irement of Act 74, Mich. P.A. 1 | 970 4-56 |
|--|--|--|--|
| For corners in Alger (County) | Located In: | Corner Code ## | FILEL |
| Public Land Survey | T <u>47N</u> R <u>22N</u> | -07 | E 9:00 a.m. |
| | T R T R T R | | APR 20 1995 |
| 2. Property Controlling in Section | S T R S T R | REMONUMENTATION | DONALD W. KINNUNEN |
| 3. Miscellaneous Property in Sec. | S T R S T R | MAY 1 0 1995 | Register of Deeds Stamp & File Number |
| | Recorded Plat | | A B C D E F G H J K L N |
| do hereby certify that under red in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance with Court of Law; established, rexpressed below: | n conformance with regulations uctions of the United States Dep a Court of Law and/or that the corth the rules of the Michigan Boarde-established, monumented, recorders, all in the same town | A. of 1970, the corner points mentioned and rules therefore as required in the parlment of the Interior, Bureau of Land rner points mentioned in lines 3, 4 and 5 d of Land Surveyors or by a Decree of a e-monumented, recovered, found as and range, may be recorded | 6 18 17 16 15 14 13 13 15 14 13 15 14 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15 |
| 07: PLS-Alfred Millard, DS, Division, Land and Timber E Bray, RLS, 1973, This corne | 1852, Set Qr. Section Post- xamination Report, R.Radcliff r was set from old signature | fe, RLS, 1949, indicates stake at co | mlock 18", S.20 W., 13 links. CCI Forestry orner position. No references given. Frank J. es: 5" Hemlock, N.52 W., 22.9 ft., 5" |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D7: Found 1 1/4" G.I.P. with 4" Alum. cap marked to identify corner position, and a squared 4" Cedar post. Found blaze lines north and south and blaze line west. Section corner to the east common to Sections 16-17-20-21 was recovered in 1993 using this corner at 40.11 chains from this corner. A search was made for original BT's at GLO BT locations and results inconclusive. 1973 report, Filing no. 34, A.C.Records states corner was established from two old signature trees and blaze line north and south and blaze line west. Found BT's of 1973 report in excellent condition. Established additional reference trees. Corner lies in flat, open area of mixed timber. Corner position is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

07: Found 1 pipe w/ 4 Alum. Cap, a fallen tree has broken edge of cap off. Stamped P.A. 345 on cap and renewed existing reference trees w/ BT signs and paint. Established new reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ brass I.D. washers in all the following reference trees. Ex. Hemlock 8", N.51 W., 22.93 feet, 'Dbl Blz', Ex. Hemlock 8", S.31 W., 13.51 feet, "Obl Blz", Twin Hemlock 6", N.38 E., 57.65 feet, '1/4s BT', Maple 11', S.31 E., 63.04 feet, '1/4s BT', Steel witness post with Survey marker sign, 5.29 W., 1.6 feet. All bearings are magnetic.

| | Ω | |
|-----------------------------|---------------|---|
| | short & James | Date 12 April 1995 |
| Signed by | | Date |
| Surveyor's Michigan License | No 25849 | FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 |
| " | • | BEVIEFO MAY 14 187 |