) F\$[	IRVEY &	
a.	L'OLL.	

DEC 27 1999

		 ٠		
For corners	in	T16	)N	

## LAND CORNER RECORDATION CERTIFICATE

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 848 of
P.A. of 1990 On 12-81999
U David

Gueld			·
Chair	·	w	

	SEVIIL	Filing Require	ement of Act /4, Micn. P.A.	1970
	Alger	Located In:	Corner Code #	<i>05-15</i> a
	(County)			inclaid
1,	Public Land Survey	T 48N R 15N T 48N R 16W	A9 M9	TIME 1:30 p.m.
	٠.	T R		DEC 1 5 1999
2.	Property Controlling in Section	T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI
3.	Miscellaneous Property in Section	ST R ST R	· •	Register of Deeds Stamp & File Number
		Recorded Plat		A B C D E F G H   J K L M
5.	Private Claims			2 6 4 3 4 3
		·		. 3
1.	Robert L. Jamros	, in a field survey on\$e	ptember 07, 1999	
da in	hereby state that under a lines 1 and 2 above were in	requirements of P.A. 74, Michigan P. n conformance with regulations and	A. of 1970, the corner points mentio rules therefore as required in the cur	rent
M	anagement or by a decree	ons of the United States Departr of a Court of Law and/or that the c	orner points mentioned in lines 3, 4	and 8 19 20 21 22 23 24
De	above were in conformant ecree of a Court of Law; es s expressed below:	ce with the rules of the Michigan E stablished, re-established, monumer	loard of Land Surveyors or to nted, recovered, fo	und 10 30 29 28 27 26 25
N	OTE: Not more than 2 on this certificate	corners, all in the same town and	d range, may be recorded	11

A. Description of original monument and accessories and/or subsequent restoration:

A9: PLS \* William A. Burt, DS, 1841. \* Set post corner of Sections 24 and 25 (T48N-R16W). \* Beech 8°, N.79 E., 52 links. \* W.Pine 12°, N.15 W., 11 links. \* No other subsequent restoration of record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A9: Located corner search area by calculated position and standard field survey. Found Maple 24", dead and down, scribed 'NBT, S25' at S.54 W., 6.3 feet, more or less, author unknown. Also found squared 6" Cedar post down and badly burned. Timber cruisers paint lines in all cardinal directions from downed post. Located GLO BT, W.Pine in the N.15 W., position. A portion of the lower blaze with axe marks and the scribing still visible. Set corner monument at S.15 E., 11 links from W.Pine stump. Corner position as established is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A9: Set 2 1/2°x30° Berntsen aluminum monument No. A1NB30 with 3 1/4° aluminum cap. \* Established the following reference trees with BT signs, blazed, scribed and painted. \* Set PK nails with aluminum I.D washers for measure in the following: Twin Maple 10°-14°, N.10 W., 5.37 feet, blazed only. \* Maple 12°, S.34 W., 28.22 feet, "S25 BT". \* Maple 8°, S.12 E., 10.38 feet, "S30 BT". \* Maple 7°, N.77 E., 22.11 feet, "S19 BT". \* Survey marker sign on 6 foot steel post, S.26 W., 1.0 feet. \* All bearings are magnetic.

Signed by talent Sams

Surveyor's Michigan License No. 25849

Date

ROBERT L.

JAMROS

PROFESSIONAL
SURVEYOR
No.

2525299