## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Alger	Located In:	Corner Code #		
(County)	_			
1. Public Land Survey		16W J1 16W K1		
2. Property Controlling in Section	S T R S T R R			
3. Miscellaneous Property in Sec.	S T R S T R		Register of Dee	ds Stamp & File Number
4. Lot No. , Red 5. Private Claims	corded Plat	10/15/2008	A B C D E	F G H I J L M
above were in conformance with instructions of the United States a Court of Law and /or that the other rules of the Michigan Boar	n a field survey on K1  74, Michigan P.A. of 1970, the regulations and rules therefore a Department of the Interior, Burdstorner points mentioned in lines of Land Surveyors or by a	09/24/2008 do hereby state corner points mentioned in lines 1 and 2 as required in the current manual of survey eau of Land Management or by a decree of 3, 4 and 5 above were in conformance with Decree of a Court of Law; established,	7 - 18 - 17 - 7	
re-established, monumented, recov		d range, may be recorded	9 10 30 29 11 12 31 32	

- A. Description of original monument and accessories and/or subsequent restoration:
- (J1) Quarter corner common to Section 2 T48N-R16W and Section 35 T49N-R16W. 1948 Reestablished by Ray J. Brotherton RLS midway between Section corners I1 and K1 and on a straight line between K1 and a positively identified Hemlock Line tree west of K1. Set 4" squared fir post. 9" Sugar N40W 17.9', 6" Beech S61E 17.7'. 6.34 chains west of the 1/4 to Log Road course N30E.
- (K1) Corner common to Sections 1-2 T48N-R16W and Sections 35-36 T49N-R16W. 1948 Perpetuated by Ray J. Brotherton RLS in the remains of a notched and burnt pine stump judged by Mr. Brotherton to be the remains of the original Gov't corner tree. No description of new monumentation was given. Witnesses: 12" Norway Pine S15E 61 links, 11" Norway Pine NO1E 36.5 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J1) The 1948 post was not recovered. Found the 1948 witnesses and at record bearing and distance, recovered the corner post hole in the ground. Also found, adjacent to the hole, a 3/4" dia. iron pin and a 5/8" rebar, set by persons unknown. Accepted the location of the post hole and NBTs as a careful and faithful reestablishment of the position of the original corner and drove a new monument, described below. into the post hole.
- (K1) Found the remains of the burnt pine stump noted in the 1948 record, at record bearing and distance from the 1948 witness trees, both in good condition with overgrown blazes. Found an old squared post, rotted off and laying on the ground, adjacent. Recovered the post hole of this post in the center of the stump and drove a new monument at that position.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

"MI DNR LS33986". S MDNR tag in the side of 18" Sugar N31W 17.88 7" Maple N86E 27.41' 19" Maple S38E 29.35' 6" Maple N30E 24.17'	pe with plastic cap stamped Set measuring nail with f: mrkd "1/4S NBT" 1948 NBT do do do	(K1) Set 1"IDx36" I.pipe Set measuring nail with 10" R.Pine N30E 4.94' 12" W.Pine N50W 27.22' 10" W.Pine S83W 24.82' 20" R.Pine S11E 40.82'	"\$35 NBT" "\$2 NBT"
Bearings are magnetic.			

Signed by Supply Surveyor's Michigan License No.

Date

05/07/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

47219

FORM APPROVED BY MICHIGAN STATE BOARD

2 A N D Schied Ly 14, 1975

STEPHAN J

LAND

YSZKOSK

JRVEYOF

47220