Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 On 12-12 19.95

Seuld Walson For corners in Chairman

Alger

2. Property Controlling

expressed below:

JAN 2 3 1996 CHAMISSION

ALGER COUNTY, MI

LAND CORNER RECORDATION CERTIFICA	\TE
Filing Requirement of Act 74, Mich. P.A. 19	70

	Located In:	Corner Code ##	
(County)			REC'D and FILED
Public Land Survey	т 49N в 13W	G9	
Fublic Land Survey	T R		DEC 2.0 1995
	T B		
	T R -		2:45 p.m. DONALD W. KINNUNEN County Clork

3.	in Section S T R			Regist	Register of Deeds Stamp & File Number									
4.	Lot No.	_ , Recorded Plat				A E	з С	D	E F	G	н	l J	ĸ	L
5.	Private Claims				2	6	I	- 5	_4-	<u> </u>	3	2	\Box	1
					3	H	_	+-1		╁┈	╁╌┤	\vdash	\dashv	4
	Dehart 1 Tamas		Tuno 21 1995	10	4		+	- 8	_ -	+	ю—-	1 ['] 1	'+	—¦
do in	hereby certify that und lines 1 and 2 above w	, in a field survey on er requirements of P.A. 74, Mich ere in conformance with regula instructions of the United State	igan P.A. of 1970, the com ations and rules therefor	er points mentioned e as required in the	6 9	18		-17	16_	H	15		4	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

S ____ T ___ R _

A. Description of original monument and accessories and/or subsequent restoration: 69: PLS-Francis Coleman, DS, 1851, Set post corner of sections 21,22,27 & 28 - Spruce 8', N.28 E., 6 links, Y.Birch 30', S.64 W., 39 links. CCI Forestry Division, Land and Timber Examination Report. Henery Carpenter, 1946, on timber cruise sheet notes a post at corner. location. No references given. T.J. McLaren, 1952 through present, Notes on timber cruise sheet a 4" post and iron at section corner location and at \$1/16 corner common to Sections 21 and 22. No references given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

69: A search was made for 4° post and iron at corner position. Iron has been lost to road maintenance. Remains of post was found near corner position. Established corner position by field survey. Found 1 5/8" axle shaft at South 1/16 corner between sections 21 and 22. Measured southerly from 1/4 section corner common to sections 21 and 22 to the South 1/16 corner and extended line southerly of South 1/16 corner the measured distance to set the corner position of G9. Measurements of the section line common to sections 21 and 22 agree very well in the North half and South half of the common section line. Found old blaze line to the west from the corner position. A search was made at GLO bearing tree positions, evidence has been lost. Corner position is accepted as a careful and faithful reestblishment of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

69: Set Berntsen Mon. no. AINB30, stamped to identify corner position. Established the following reference trees w/ BT signs, blazed, scribed and painted. Set PK mails for measure w/ Alum. I.D. washers in the following reference trees. Cherry 7, 5.63 E., 54.83 feet, S27 BT ", Maple 11", N.76 E., 123.53 feet, " S22 BT ", W.Pine 6", S.56 W., 44.33 feet, " S28 BT ", W.Pine 8", N.49 W., 45.71 feet, S21 BY *, Survey Marker sign on six foot steel post, N.90 W., 8.0 feet. All bearings are magnetic.

JAMROS LAND SURVEYOR NO. /

ROBERT

BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN .. 1983