SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Remonumentation Peer Group Under Act 345 of P.A. of 1990 Cn 12-10 199 Gerella Colson

FEB 1 9 1998

SECTION LAND CORNER RECORDATION CERTIFICATE

05-8

Chail nam	Filina Reauiren	nent of Act 74, Mich. P.	A. 1970
For corners in	Located In:	Corner Code #	F.LID TIME <u>8:30 A.m.</u>
Public Land Survey	49 13 T 4N R 1111 T R T R	14 	DEC 17 1997
 Property Controlling in Section Miscellaneous Property in Section 	T R S S T R		DONALD W. KINNUNEN REGISTER OF DEEDS GER COUNTY, MI Register of Deeds Stamp & File Number
	, Recorded Plat		2 6 5 4 3 2 1 1 1 1 1 2 1 2 1 1 1 1 1 2 1 2 1 1 1 1 1 2 1 2 1 1 1 1 1 2 1 2 1 1 1 1 1 1 2 1 2 1 1 1 1 1 1 2 1 2 1 1 1 1 1 1 2 1 2 1 1 1 1 1 1 1 2 1

5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the comer points mentioned in lines 3, 4 and

_, in a field survey on

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I4: PLS - Francis Colman, DS, 1851 * Set quarter section post * Cedar 10, N.29 W., 30 links, Cedar 12, 8.45 E., 10 links ***** T.J. McLaren, C.C.I. Co., Land Corner Records, 1963 * Set post and Iron * Could find no remains of original Er's * Witnesses - Cedar 12, N.52 E., 6.2 feet * Cedar 8, N.83 W., 3.5 feet * Unrecorded report. ***** No other subsequent restoration on record.

October 14, <u>1997</u>

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

14: Located corner position by field survey * Position lies in low area East of Grand Marais Creek * Evidence of a paint line running East from corner position * Grand Marais Creek lies South of corner position approximately 235 feet, GLO calls for 218 feet * Found 4 inch squared post, S.48 N., 35.8 feet from corner position, and Iron of the 1963 unrecorded report was never found * Evidence at GLO original BT locations was not found. * Made search of area around corner position for remains of original post * Established corner position on true line at mid point between section corners North and South * Corner position is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

14: Set Berntsen Alum, monument no. AINB30, stamped to identify corner position * Established reference trees w/87 signs, blazed, scribed and painted * Set PK nails w/Alum. I.D. washers in the following - Balsam 5, S.09 E., 3.5 feet, '1/48 81' * Cedar 12, N.33 E., 18.12 feet, "1"45 BT" * Cedar 12, N.25 W., 11.81 feet, "1/45 BT" * Cedar 14, S.57 W., 42.55 feet, "1/45 BT" * Survey marker sign on 6 foot steel post. #.34 E., 1.1 feet * All bearing are magnetic.

Signed by 25849 Surveyor's Michigan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 EVISED MAY 14, 1975 REVISED JAN., 1983

innos. ROFESCIÓNAL SUNVEYOR