SURVEY & REMONUMENTATION

Approved by Alger County Land Survey Flomonumentation Peer Group Under Act 345 of A. of 1990 On 5/8 1990

JUL 3 0 1996

P.M. 01	
	1000
	sald Welson
	Chairman
	1 / 13/25/11/10/25/1

LAND CORNER/RECORDATION CERTIFICATE

Chairman	Filing Requirement of Act 74, Mich. P.A. 1970			
For corners in				
Alger (County)	Located In:	Corner Code #	, , ,	
			FILED	
Public Land Survey	T <u>49N</u> R <u>13W</u> T R		TIME 3:00 p.m.	
	T R T R		JUN 27 1996	
2. Property Controlling in Section	ST R ST R		DONALD W. KINNUNEN REGISTER OF DEEDS	
3. Miscellaneous Property in Section	ST R ST R		ALGER COUNTY M Register of Deeds Stamp & File Number	
4. Lot No	, Recorded Plat		A B C D E F G H I J K L M	
5. Private Claims				
			3	
			4 7 8 9 10 11 12	
,Robert L. Jamros	, in a field survey onNa	<u>irch 06, 1996</u> , 19	5	
do hereby certify that under i	requirements of P.A. 74, Michigan	P.A. of 1970, the corner points men	tioned 8 18 17 16 15 14 13	
		d rules therefore as required in the or rtment of the Interior, Bureau of		
		comer points mentioned in lines 3,		
		Board of Professional Surveyors or ented, re-monumented, recovered.	· · · · · · · · · · · · · · · · · · ·	
as expressed below:	stabilistied, re-establistied, monum	ented, re-monumented, recovered,	10 30 29 28 27 26 25	
NOTE: Not more than 4 o	corners, all in the same town a	nd range, may be recorded	11	

A. Description of original monument and accessories and/or subsequent restoration:

M2: PLS-John Burt, DS, 1841, Set qr. section post - Cottonwood 2°, S.84 E., 29 links, Aspen 10°, N.14 W., 35 links.***** Michigan Department of Natural Resources, Billy D. Buckler, RLS, 1975, Corner re-established on line and by single proportion measure. Found squared post 7.35 feet north and 3.95 feet west of corner position. Set 1" iron pipe with 4" Aluminum cap, Established the following references - W.Pine 10", S.25 W., 22.4 feet, R.Pine 14", N.27 W., 42.7 feet. Recorded in Liber one on page 215, Luce County Records.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M2: Found 1 " G.I.P. with 4" Aluminum cap and a 4" flat faced wood post, scribed. Also found two existing bearing trees as described in the report of 1975. Existing W.Pine BT in the southwest position is now a dead stub. Information acquired from the Michigan DNR documenting the method at which corner position was reestablished follow accepted methods. Renewed existing bearing tree to current Alger County standards and established additional reference trees. Monument is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M2: Stamped P.A. 345 in existing four inch Aluminum capped Department of Conservation Monument. Renewed existing reference tree w/ BT signs and paint. Established additional reference trees w/ BT signs, blazed, scribed and painted. Set PK nails for measure w/ Alum. I.D. washers in the following reference trees. Ex. Red Pine 20°, N.21 W., 42.85 feet, "1/4s NBT", Red Pine 8°, N.43 E., 50.54 feet, "1/4s BT", Red Pine 15°, S.51 E., 54.92 feet, "1/4s BT", Red Pine 7°, S.24 W., 25.92 feet, "1/4s BT", Survey marker sign on six foot steel post, 5.68~W., 1.0~feet.~All~bearings~are~magnetic.

Signed by_ Surveyor's Michigan License No.

No. 23239 FORM APPROVED BY A

ROBERT L **JAMROS** PROFESSIONAL SURVEYOR

> REVISED MAY 14, 1975 REVISED JAN., 1983