		LAND C	ORNER RECORDATIO	N CERTIFICATI	E					
For	corners in	Filing R	equirement of Act 74	Mich. P.A. 1976	0					
	(County)	Located In:	Corner Code	#						
1.	Public Land Survey	T <u>49N</u> R <u>1</u> T <u>49N</u> R <u>1</u> T R _								
3.	Property Controlling in Section Miscellaneous Property in Sec.	T R _ S T R _ S T R _ S T R _		R	egister o	Deed	s Stamj	& File	Numb	er 
		Recorded Plat			- <u>^</u>	вс	D E F	G H		L M
in lin curr Man abov Cou expr NOT	nes 1 and 2 above were is ent manual of survey instruagement or by a decree of we were in conformance with of Law; established, ressed below:  TE: Not more than 4 con this certificate  Description of original	, in a field survey on quirements of P.A. 74, Michign conformance with regulat ructions of the United States a Court of Law and/or that the the rules of the Michigan re-established, monuments corners, all in the same to	gan P.A. of 1970, the corner pions and rules therefore as a Department of the Interior, e corner points mentioned i Board of Land Surveyors or ed. re-monumented, recovown and range, may be ries and/or subsequent r	oints mentioned required in the Bureau of Land n lines 3, 4 and 5 by a Decree of a ered, found as recorded	3 4 5 6 1 7 8 11 2 3 13 1 1 12 3 13 1 1 1 12 13 13 1 1 1 1	9 2 0 2 1 3 Billy	7 16	10—15—15—22——27——34———16er, RL:	23-26-35-35-35-35-35-35-35-35-35-35-35-35-35-	-12
(C9)	Corner common to Secti	ine M65W 84 links, 11" Re ions 19-20-29-30. Corner E 92 links, 8" Red Oak S3	remonumented in the orig	inal position in	1956 by B	illy D	. Buckle	r. 1"	oipe wi	th 4"

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (89) Recovered the 1957 monument, in good condition, at record bearing and distance from the 1957 MBTs: The Red Pine is in good condition and the White Pine is a cut stump. Left the monument in place and warked new witnesses as described below. An E-W trail is 15' north of the monument.
- (C9) Recovered the 1956 monument at record bearing and distance from the record R.Pine NBT, in good condition, and the Oak NBT, now a cut stump. Found no evidence of the original BT noted in the 1956 record. Left the monument in place and made new witnesses as described below. An E-W trail is 16' north of the monument.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(B9) Found 1" pipe with 4"	brass cap.										
Blazed, scribed, and set me	easuring nails										
in the following:											
20" R.Pine N30E 33.75' 1	/4S NBT"										
6" N. Birch N68W 52.05'	do										
5" R. Pine N50W 39.45'	do										
5" R. Pine East 50.95'	do										
Bearings are magnetic. Distances are to											
nail with tag.											

(C9) Found 1" pipe with 4" brass cap. Blazed, scribed, and set measuring nails in the following: 16" R.Pine N35E 60.45' "S20" (1956 NBT) 6" W.Pine N26W 8.4' "S19" 8" J.Pine N78W 7.25' "S19" 10" W.Pine S28E 32.3' "S29" Bearings are magnetic. Distances to nail with tag.

