, d		SURVEY &	
٤_	RE!	Wagnessen A. JOH	V.134

DEC 2 7 1999

or corners in	SECTION	LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74, Mich. P.A. 197

Approved by Alger County
Land Survey Remonumentation
Peer Group Under Act 345 of P.A. of 1990 On 12-8 19 99
P.A. of 1990 On 12-8 1999
Level a Color
Les el Color

Chairman

05-	145
<i>ల</i> క -	170

	• •		
ALGER	Located In:	Corner Code #	05-145
1. Public Land Survey	T 49N R 13W T 49N R 14W	A8 MB	TIME
•	T R T R	<u> </u>	DEC 1 5 1999
 Property Controlling in Section Miscellaneous Property in Section 	S T R S T R S T R S T R		DONALD W. KINNUNEN REGISTER OF DEEDS ALGER COUNTY, MI Register of Deeds Stamp & File Number
	Recorded Plat		A B C D E F G H I J K L M
do hereby state that under red	in a field survey on quirements of P.A. 74, Michigan P.A. conformance with regulations and ru	of 1970, the comer points med les therefore as required in the	entioned 6 18 17 16 15 14 13 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Management or by a decree of above were in conformance	is of the United States Department a Court of Law and/or that the core with the rules of the Michigan Boardblished, re-established, monument	ner points mentioned in lines 3 ard of Land Surveyors	3, 4 and 8 19 20 21 22 23 24 or by a d, found 10 30 29 28 27 26 25
NOTE: Not more than 2 co	orners, all in the same town and	range, may be recorded	11 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration: A8: PLS * John Burt, DS, for William A. Burt, DS, 1841. * Set quarter section post * Tamarack 8", S.61 W., 117 links (only 1 reference shown in notes of 2 townships). ***** George L. Depew, CS, 1917. * Set iron corner on true line between section corners, overall distance 5278 feet. * No references. ***** Michigan State Highway Department, 1958, Highway Improvement Plans of M-77. * At highway station 689+35 feet, approximate East-West quarter line shown, no corner position shown. ***** No other subsequent restoration on record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A8: No corner monument found. * Established corner position at mid-point and on line between section corners North and South. * GLO stream calls of 1 chain South, stream, 4 links, C-E AND 1 chain North, stream, 2 links, C-E, have been relocated into 1 stream crossing by culvert, 39 feet South of corner position. Area around highway and corner position is an open marsh and original BT has been lost. * Corner position as established is accepted as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A8: Set 5/8°x18' rebar with Berntsen 3 1/4° aluminum cap No. RBD 5325, stamped to identify corner position. * Established the following references: Power pole, S.27 E., 84.05 feet to a PK nail with aluminum I.D. washer. * West end of 36" C.M.P. culvert, S.27 W., 40.83 feet to a PK nail with aluminum I.D. washer. * East end of 36° C.M.P. culvert, S.47 E., 56.62 feet to a PK nail with aluminum I.D. washer. * Centerline of asphalt pavement on highway M-77, East, 15.6 feet. * No survey marker sign set along highway. * All bearings are magnetic.

Signed by Surveyor's Michigan License No.

OF MIC ROBERT L. JAMROS PROFESSIONAL SURVEYOR