APR 2 5 1995

## COMMISSION

## ALLEGAN COUNTY REMONUMENTATION I AND CORNER RECORDATION CERTIFICATE

|        | 001111611 |        | 1104110 |       |      | ~    |
|--------|-----------|--------|---------|-------|------|------|
| Filing | Requirem  | ent of | Act 74. | Mich. | P.A. | 1970 |

For corners in Allegan Located In: Corner Code ≠# T 1N R 13W G-7 1. Public Land Survey Sec. 15, 16, 21 & 22 Cor. 22 В R 즋 Trowbridge R 2. Property Controlling Twp. in Section S. 3. Miscellaneous S \_ R \_ Register of Deeds Stamp & File Number Property in Sec. S \_ R \_ \_\_\_\_, Recorded Plat 5. Private Claims \_ I. <u>Kink Van Onden</u>, in a field survey on <u>May 25</u> 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawland/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: APPROVED REMONIMENTATION CORNER P.A. 345 OF 1990 ALLEGAN COUNTY •GLO set post at 80.00 chains North of G-9. 20" Sugar S85°W 38 links DATE APPROVED 6-14
COUNTY REP. Kind 6-74 18" Sugar N35°E 31 links

(Continued on back of sheet)

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fd. 1" x 22" steel pipe using info. from Ratekin and Van Order surveys. Did not find stone. Road appears to have been cut to the West and filled to Did not find stone. Road appears to have been cut to the West and filled to the East to decrease the grade. Stone may have been removed due to road construction. Dug trench 2' North of found pipe but could not locate stone. Nail in W side RR Tie corner fence post S 26.92' Nail in NE side 18" Maple SE 28.92' Nail in SE side 7" Maple N,NE 32.02' Nail in 9" Ash NW 29.80' C/L Gravel Road 5.007 N And is accepted as a careful and faithful perpetuation of the position of the original corner. Peer Group approved 6-14-94.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced steel pipe with a standard Allegan Co. Remon. monument (3/4" x 36" steel rod w/red cap #23520)

Nail & Remon. tag in NE side 18" Maple SE 28.98'

Nail & Remon. tag in NE side 12" Ash S,SE 42.33'

Nail & Remon. tag in SW side 15" Ash N,NW 36.12' Nail & Remon. tag in SE side Twin 15" Maple

12-30-74 Signed by

Surveyor's Michigan License No. .

11612 0005 PAGE 158

Page 1 of 2

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

eferie a -

## Section A (continued from Page 1)

```
•Old survey notes show at corner a pointed sand & flint stone, 12" or 14" long w/"X" on flat side, point up.

8" Elm N

14" Sugar Maple SW

Other ties show:

14" Elm N,NW 22'

Fence Post N 30.4'

Fence Post S 29'

•Ratekin witness card shows

3/4" Pipe, SE Cor., Sec. 16

RR Tie Cor. Post S 26.5'

9" Maple S35°E 28.7'

22" Maple S60°W 48.1'

3" Maple S30°W 34.9'

•Ratekin survey (V-16-4) 3-30-1972 shows same witnesses above

•K.V.O. survey (93-2974) 8-18-1993 shows a 1" pipe found

Nail in W side RR Tie corner fence post S 26.92'

Nail in NE side 18" Maple SE 28.92'

Nail in SE, side 7" Maple N,NE 32.02'

Nail in 9" Ash N 29.80'

C/L Gravel Road N 5.00'
```