## 1 PAGE 283 1993 ALPENA COUNTY REMONUMENTATION CORNER

007997

			RECONDITION CE				KUE		, - <del></del> -		
For corners in	Filin	g Requirer	nent of Act 74, Mich	. P.A. 1970	ALPE	NA U	UUNI	1 1	11.		
				1							
Alpena (County)	Located In:		Corner Code ##		Dec 16 10 19 AM '93						
			_		DEL H	טו נ	To H	II J	IJ		
Public Land Survey	T 32N F	R _ <b>8E</b> _	<u>I - 9</u>		<b>\</b>		۸.				
	T R				REGISTER OF DEEDS						
											T F
	2. Property Controlling	S T F	}								
in Section	S T 1	₹									
3. Miscellaneous	S T I	₹	·	Regist	er of D	eeds S	itamp	& Fil	e Nu	ımbeı	r
Property in Sec.	S T I	· · · · · · · · · · · · · · · · · · ·			<del></del>				<del></del>		
4. Lot No, R	ecorded Plat	·			А В	C D	E F	G H	1	JК	L
5. Private Claims							Ī		$\top$	TT	$\top$
				2	ĭ	├─ 5 	1-1-	- 3 1	_	2	-1
				3	<b> </b>	<del>                                     </del>	<del>                                     </del>	╁╌┼	+	+	-
				· 4	├ <b></b> ?	<del>├</del> ─ ∳─	<b>ģ</b>	10-		-11-	—į:
Duane R. MacNeill	, in a field survey on	Ju	, 19 <u>19 19 19 19 19 19 19 19 19 19 19 19 19 1</u>	93 5	·		┼┼┼╌	╁┷┼	-	++	-
do hereby certify that under req in lines 1 and 2 above were in	juirements of P.A. 74, Mi	chigan P.A. o	t 1970, the corner points m	entioned e	18-	-17-	16	15	-	-14	∳
in lines 1 and 2 above were in	comormance with reg	ates Denartn	rules therefore as requirement of the Interior. Bureau	u of Land	·	<u> </u>	<u> </u>	1		$\dashv$	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5						20-	  21	22	Щ.	-23	J
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						LÏ	IÌ	LΪ	丄	لــــــــــــــــــــــــــــــــــــــ	$\bar{\perp}$
Court of Law, established, re-established, monumented, re-monumented, recovered, found as								Ţ	T		
expressed below:				1( tad 11	1 %	29-		1		î	
NOTE: Not more than 4 corners, all in the same town and range, may be recorded				160			17	t		$\top$	ヿ
on this certificate.				12	1 "	32	33-	34	十	35	30 
				16 Hone		L	L			<del></del> -	L
A. Description of original a								_			
<u> 1855</u> - Cedar Pos	it	<u> 1901</u> -	Reported by Cou		******	<u>939</u> -	- 6x6				
			Leroy as being '	"Well Estab	-					set	
Witnesses:			lished"							rvey	or
Hemlock 12 S	48 W 26		Witnesses:					eil.		No roc	·Ar

Cedar fence Post 8 S 44 E 54 1/2

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 6x6 concrete monument East of the Center line of Long Lake Road. Witness tags found surrounding location. Monument has been referenced upon several recorded surveys.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Monument lowered to approx. 9" below road surface. Appropriately stamped Alpena County Remonumentation Aluminum Cap secured on rerod in center of monument.

## Witnesses:

N 60° E 36.01' Power Pole Fd. N 82° W STRUCTURE OF MAN 34.31' Power Pole Fd. Tel. Pole Fd. S 66° W 40.24' S 16° E 51.40' 12" Maple Set

9 N 77 1/2 E 5

Witnesses were freshened as necessary, and nails replaced with duplex nails bearing a brass washer stamped License # 19237

Date \_

December 6, 1993

19237 Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19 REVISED JAN., 19