## Arenac County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

02 PAGE 57 1975

in	Filing Requirem	ent of Act 14, Mich. P.A. 19	
corners inArenac	Located In:	Corner Code*#	ARE 2
Public Land Survey	T <u>18N</u> R <u>4E</u> T R	G 10	2 L
Property Controlling	T R T R ST R		DEEDS SEEDS
in Section Miscellaneous Property in Section	S T R S T R S T P		Register of Deeds Stamp & File Number

5. Private Claims L Craig W. McVean May 26 . in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a

Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

<u>G 10</u> - Set 1/4 Section Post - J. Burt - 1843. B. Ash 11" S 30° N 4 Lks. Elm 9" N 55° E 32 Lks.

1.

4. Lot No.

Arenac County Surveyors Notes - Referenced corner - distance tie E to I 10 - 1903. Etc 110 - 1903. <u>L.C.R.C.</u> - L. 1, P. 49 - 1/2" iron - McGinnis - 1973, <u>Recorded Surveys</u> - L. 1, P. 88 - set iron - McGinnis - 1973; L. 1, P. 106 - found iron - 1973.

\_, Recorded Plat

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G 10 - Find lite reaction at centerline - centerline intersection of roads E, W, N, and S. Excavated and find well preserved 2" x 1.5" x 14" long post near surface. Excavate reaction to SE and find top of 5/8" iron rod - 0.55' SE of post - down 1.4'. Remove 5/8" x 1.1" long iron rod - find stone -down 1.7'. Excavate more and find another very rotten wood post under first wood post down 2. Remove 2" dia. x 5" of very rotten post with point - stake falls apart - find 4 cobble size granite stone around bottom post location - dig down 2.5' - find no other evidence - bottom wood post as original corner. Set 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic sleeve with concrete in place of wood down 0.5', place 4 found cobbles around monument. Monument accepted as a careful and faithful perpetuation of the position of the original

Reference Point "A" - found LS cap 27595 on 1/2" x 18" rebar at location of 1/2" iron per L.C.R.C. L. 1, P. 49 and 2 recorded surveys noted "A". Location agrees with 3 recorded Witnesses. Excavate down 2' into road and clay and find no other evidence to support monument. Mor was established using improper procedures and is not utilized in this survey - reset 1/2" rebar and cap.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G 10 - 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic tile sleeve with concrete.
S 65° E 35.75' to capped 3/8" rebar.
N 23° E 35.98' to capped 3/8" rebar.
S 52° W 43.44' to nail and tag in SE side wood anchor post.
N 54° W 33.92' to nail and tag in N end 18" CMP.
S 85° W 140.25' to nail and tag in N side 10" Apple.
N 46° 24'30" W 4.89' to Reference Point "A" - capped 1/2" rebar.

ACCEPTED BY THIS ARE SURVEY PEER GROUP AS CORNER INDER MICHIGA

OF MIC CRAIG W. McVEAN AOFESSIONAL ROYEVRUE No 39088 SESSIUMAL Songe Session

Surveyor's Michigan License No.