

FFR 1 8 1994

Arenac County Remonumentation

COMMISSION LAND CORNER RECOR			TION CERTIFICAT	E LIBER	02PA	ge 014	:
For corners in Arenac	Filing Requ	irement of Act	74, Mich. P.A. 197	'0		Dec -22	7 2
(County)	T18N R4 T T18N R4 T T18N R	E 1-12 E 1-13			Manage Sept.	2 16 11 193	ECORDED
2. Property Controlling in Section	S T R S T R				<i>,,</i>	ස	
3. Miscellaneous Property in Sec.	S T R S T R		R	legister of Dee	ds Stamp	& File Nu	ımber
	Recorded Plat			2 A B C	D E F	G H 1	J K L W
Craig W. McVean	Se, in a field survey on	ptember 2	93	4 7 7 1	- 8 9	10-10-1	
to hereby certify that under a n lines 1 and 2 above were current manual of survey insulations above were in conformance court of Law; established expressed below:	requirements of P.A. 74, Michigan Fain conformance with regulations structions of the United States De of a Court of Law and/or that the cowith the rules of the Michigan Boa, re-established, monumented, corners, all in the same town	P.A. of 1970, the corner and rules therefore partment of the Interference price price points mentioned of Land Surveyors re-monumented, re-	er points mentioned as as required in the rior, Bureau of Land ed in lines 3, 4 and 5 s or by a Decree of a covered, found as		-17 16 16 17 16 17 16 17 18	-15 -22 -27 -34-	-14 13 23 24 26 25 25 35 36
A. Description of original	al monument and accessories	'	nt restoration:	13	1 1 1	1	1-1-1-

1973; L. 1, P. 320 - 1977. Unrecorded Surveys - Harrison surveys - Survey No. 8105793 - 1981; Burgin Land Surveys - Job #580424 - 1988.

M.D.O.T. ROW map File #6-R-2, Project 6-21, Sheet 17.

Recorded Surveys - L. 1, P. 368 - 1978; L. 1, P. 102 -

Tamarack 10" N 83° E 45 Lks. Tamarack 14" N 22° W 37 Lks. County Surveyor notes - 1923 - wood post, M.D.O.T. ROW map File #6-R-2, Project 6-2, Sheet 17. Recorded Surveys - L. 1, P. 102 - 1973; L. 1, P. 368 - 1978; L. 1, P. 320 - 1977.

Description of corner evidence found and/or method applied in restoring or reestablishing corner: 1-12 Found PS Cap #29240 on 'T' iron per Burgin unrecorded survey. Burgin replaced PK nail remains in agreement with L. 1, P. 368. Excavated 'T' iron. Found square 16" x 16" form in concrete under bituminous at apparent location of former mon. box per recorded surveys. Mon. box apparently destroyed during removal of concrete lane divider. Accepted monument as best available evidence of the position the original corner. Accepted by Arenac County Peer Review Group on 12-8-93.

Reference Pt. 'A' - Nail and tag per unrecorded survey by Harrison surveys. Not in agreement with recorded surveys. Was established using improper procedures and is not utilized in this survey.

I-13 Standard corner common to Sec. 34 and 35, T18N, R4E. Found 3/4" x 24" bar in mon. box per recorded surveys and M.D.O.T. ROW sheet. Monument accepted as the best available evidence of the position of the original corner. Accepted by Arenac County Peer Review Group on 11-17-93,

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-12 Replaced 'T' iron with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box.

W. Pine 30" N 5° E 25 Lks.

N 77° W 125.71' to SE corner House #5748.

S 45° E 88.77' to nail and tag in W side 8" Pine.

S 90° E 125.78' to nail and tag in N side 24" twin tree.

N 45° E 99.65' to SW corner House #9965.

N 25° E 179.67' to nail and tag in E side U.P.

Reference Pt. 'A' 1' N and 1.5' W - nail and tag.

1-13 Replaced bar with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box.

S 20° W 136.60' to nail and tag in N side U.P. N 30° W 226.18' to nail and tag in E side U.P.

S 75° E 130.79' to nail and tag in W side U.P.

S 25° E 116.50' to nail and tag in W side 14" tree.

E 7.92' to 2-3/4" Bay County brass cap in mon. box (I-1 - T17N -

Date

OF MICHIGAN CRAIG W MCVEAN **PROFESSIONAL** SURVEYOR No.

39088 OF LAND SU OFESSION

9088 Surveyor's Michigan License No.