For corners in	Fill	ng Requirement of Act 74, Mi	CN. P.A. 1970								
_											
(County)	Located In:	Corner Code #									
(COURTY)											
1. Public Land Survey	T_47H R T_47H R T R T R T R	33W A11									
2. Property Controlling in Section	s TR s TR										
3. Miscellaneous	S TR										
Property in Sec.	<u> </u>			Re	gister	of Dec	ds St	amp &	File	Yumi	Der
4. Lot No, Record				, A 1	вс	D E	F	з н	I J	к	L M
5. Private Claims				1		ŢŢ	1	Ţ	ŢŢ		ŢŊ
		Tul. 02. 2001		3	ì	1	-1-	_ i_	Τí	$\top$	i
. Ctanhan I Czyszkoski		Jul 02 2001		- 1		ŢŢ		٦			
, Stephan J. Szyszkoski ,	in a field survey on PA of 1970 the com	, 19 do hereby str ner points mentioned in lines 1 and 2 a	shove were in	4		۱	_ 9 	10-	† 'i'		-12
conformance with regulations and r	rules therefore as requir	red in the current manual of survey instr	uctions of the	5		11	1-	- -	11		
United States Department of the In	terior, Bureau of Land I n lines 3. 4 and 5 abovi	Management or by a decree of a Court of were in conformance with the rules of	the Michigan	6 -1	8-1-	17-	-16 	15	1-14	_	-13
Board of Land Surveyors or by	a Decree of a Court	of Law; established, re-established, r	monumented,	7		11	- -				
recovered, found as expressed bek	DW:			8 -1	9	20	-21 	22_	1 - 23	_	-24
NOTE: Not more than 2 come	ers, all in the same to	wn and range, may be recorded		9	$\neg$	++	+		T		+
on this certificate.			:	1 🛖 3	<b>○</b>	29	28 	27- 	1-26	1	-2 <sup>5</sup>
			:	19-		++		- -	11	$\top$	17
				12 -3	1	32	_33 <u></u>	34-	<del>  3</del> 5	_	-36
(A10) Quarter corner common to	o Section 25 T47N-R ne with 4° aluminum	ries and/or subsequent restoration 34W and Section 30 T47M-R33W. 1 cap. 10" Hard Maple S42E 23.1 and 30831 T47M-R33W Previous)	: Corner reestab ', 10" Soft ma	ple S4	3W 28	.0'.					
(A10) Quarter corner common to Billy D. Buckler, RLS. 1" pi (A11) Corner common to Section	o Section 25 T47N-R pe with 4" aluminum ns 25&36 T47N-R34M	R34W and Section 30 T47N-R33W.	: Corner reestab ', 10" Soft ma y recorded in	lished ple Se 1981 1	3W 28 y K.L	.0'. . Sack	ett, I	RLS as	being		
(A10) Quarter corner common to Billy D. Buckler, RLS. 1" pi (A11) Corner common to Section monumented with a Northern Pa	o Section 25 T47N-R pe with 4" aluminum ns 25&36 T47N-R34N per Mills monument	(34M and Section 30 T47M-R33M.  I cap. 10" Hard Maple S42E 23.1  and 30&31 T47M-R33M. Previously  and the following 1981 accessor  method applied in restoring or rees	: Corner reestab. ', 10" Soft ma; y recorded in ies: 7"Sugar	lished ple S4 1981 i S10E 2	3M 28 by K.L :1.8',	.0'. . Sack 6" Su	ett, I gar Si	RLS as 33W 9.7	being		
(A10) Quarter corner common to Billy D. Buckler, RLS. 1" pi (A11) Corner common to Section monumented with a Northern Parameter with a Northern Parameter (A10) Recovered the 1966 monumented bearing and distance f in place and made new witness (A11) Recovered the Northern	pe with 4" aluminum ns 25&36 T47N-R34M per Mills monument  mence found and/or r ment, a 1" ID iron rom the 1966 MBTs. es as described be Paper Mills monume and at record beari	AS4W and Section 30 T47H-R33W.  In cap. 10" Hard Maple S42E 23.1  In and 30&31 T47N-R33W. Previously  In and the following 1981 accessor  In the following 1981 accessor  In the Sugar SE is in good condition.  Int, a 1"ID iron pipe capped with and distance from the 1981 accessor	Corner reestable  7, 10" Soft may y recorded in ies: 7"Sugar tablishing corne ot. of Conserva	lished ple S4 1981 I S10E 2	3M 28 y K.L 1.8',	.0°. . Sack 6" Su , in g and c	ett, I gar Si ood c lown.	RLS as 33W 9.7 ondition Left	being	d at nume	nt

33986