LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #		
1. Public Land Survey	T 47N R 34V T R	W K5		
2. Property Controlling in Section	S T R S 13 T 47N R 34V S T R	M 5		
3. Miscellaneous Property in Sec.	S T R R	Charles on the control of the contro	Register of Deeds Stamp & File Number	
4. Lot No. , Red 5. Private Claims	corded PlatK5	02/26/2009	A B C D E F G H I J K L 2 5 5 4 3 2 1	м
I, Stephan J. Szyszkoski, in a field survey on 5 08/25/2009 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 re-established, monumented, recovered, found as expressed below:				
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and r	ange, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	_

- A. Description of original monument and accessories and/or subsequent restoration:
- (K5) Corner common to Sections 11-12-13-14. 1852 Established by Z.B.Searles Deputy Surveyor. Set post. Spruce 10" S31E 17 links, Spruce 12" N87 1/2W 41 links. March 1958 L2 P211, J.P.Smallwood RLS found 4" sq'd spruce post. 5" Spruce S65E 14.00', 6" Spruce East 16.35', 9" Spruce N05E 16.40'. 1979 - L1 P377, Reestablished by K.L.Sackett RLS from M.S.H.D. stationing and R.O.W. markers. Set 1"IDx36" iron pipe with 4" alum. cap in sphagnum moss area. No available NBTs. Corner falls 45.15' west of US 141 and Sta. 1640 + 13.83. R.O.W. Marker West 54.8'.
- (5-Sec. 13) North 1/16 corner, Section 13. Not established in the original survey.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K5) Recovered the 1979 monument disturbed, bent over and flush to ground. Recovered the base of the monument, plumb and apparently in the original position, at substantial record bearing and distance from the R.O.W. Marker to the west. Accepted the position as the best available evidence of the position of the original corner.
- (5-Sec. 13) Established the corner midway and on a straight line between Quarter corner 1297.26' north and the intersection of 1/4 lines of Section 13, 1297.26' south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Tamarack S40W 26.1' mrkd "S14 NBT" 5" Tamarack N89W 22.05' "S11 NBT" 3" B. Spruce N44W 21.9' "S11 NBT" Conc R/W marker is N87W 54.8' to WEST face. Bearings are magnetic. Set sq'd post adjacent.

(5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: mrkd "1/16S BT"

2" Maple S11W 1.65' 3" Maple N69W 11.3'

do

3" Maple N23W 8.85'

do

STEPHAN J

SURVEYOR

CAND S

YSZKOSK LAND

3" Spruce S74E 26.65'

Set sq'd Cedar post adjacent.

Bearings are magnetic.

Surveyor's Michigan License No.

09/22/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD

sed Jan., 1983

16298 16306

Rervised Oct., 1995