LAND CORNER RECORDATION CERTIFICATE

	Filir	ng Requirement of	of Act 74, Mich. F	P.A. 1970							
For corners in											
Baraga	Located In:	Corner Code	#								
(County)				1							
1, Public Land Survey	✓ T <u>48H</u> R T R T R T R			į							
Property Controlling In Section Miscellaneous Property in Sec.	S TR S TR S TF S TF	$ \stackrel{\cdot}{=} =$			Re	giste	of Dec	ds Sta	imp &	File N	lumber
4. Lot No, Reco	orded Plat				1 A	3 <u>c</u> I T	D E	F G	_н_	ı J	K L
5. PRVate Claims					2	┆┼	- \$ - 	-1-1	ڊ ا		
		Apr 22 1998			3	\vdash	-		_		77
L Stephan J. Szyszkoski	_, in a field survey or	n 19_	do hereby state th	hat under	1	? 	- e -	_ ;	10 	Τï	
requirements of P.A. 74, Michi	igen P.A. of 1970, the co	THE POINT THE MOTOR	and of survey instruction	ons of the	5	$\vdash \uparrow$	<u>-j-</u> †		ij		
United States Department of th	e kitelior, durasu oi care		with the rules of the	Michigan	6 -	B	-17-		_,,_	Πï	
United States Department of the Interior, Bureau of Land Namespartment of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan that the corner points mentioned in the Michigan that the corner points are stablished, monumented, and of the michigan that the corner points are stablished, and the michigan that the corner points are stablished, and the michigan that the corner points are stablished, and the michigan that the corner points are stablished, and the michigan that the corner points are stablished.					в —		_20_		22 	<u> </u>	, _ ₂ ,
	orners, all in the same t	own and range, may	be recorded		9 —				77		
on this certificate.	E	_			10	30	29 				
					11	1			Ţ		ا ا

A Description of original monument and accessories and/or subsequent restoration:

(G5) Corner common to Sections 9-10-15-16. Corner remonumented at the original position by Billy D. Buckler in 1957: Replaced corner from one yellow birch stump bearing N62W 60 links. Traces of notch and several axe marks. Found remains of yellow birch stump S69E 31 links. Several old cruisers blazes in area. Cedar post in place. 1" pipe with 4" brass cap. Witnesses: 10" W. Pine M75E 41 links, 9" Soft Maple SI4# 48 links".

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(65) Recovered the 1957 monument, a i" 10 iron ripe capped with a 4" dia. brass Michigan Dept. of Conservation tablet, in good condition, and at record bearing and distance from both of the 1957 witnesses, in good condition. The remains of the Y. Birch noted in the 1957 record N62M were recovered at record bearing and distance. Left the monument in place and marked two new witnesses as described below. Corner recovered and remitnessed by 8. Wheeler and D. Lampela, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

(65) Found 1 pipe with 4 brass cap.

The 1957 mitnesses are as recorded.

Blazed and scribed the following new

bearing trees:

12" W. Spruce M18E 20.9" SIO NOT "S9 NBT"

6" Maple M29W 19.9' Bearings are magnetic. Distances to

notch in lower blaze.

STEPHAN . SZYSZKOSKI LAND SURVEYOR MINISTER NO.

33986 Surveyor's Michigan License No.

For the Michigan Department of Matural Resources - Forest Management Division