LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		•	1								
Baraga	Located in:	Corner Code #									
(Courty)		33,101 3333 11									
1. Public Land Survey	TR_ TR_ TR_										
Property Controlling in Section Miscellaneous Property in Sec.	S 16 T 48H R S 16 T 48H R S T R S T R	32N 4		Regi	ster o	f Dead	ls Sta	ımp &	File	Numt	901
4. Lot No, Reco				A B	Сп	E	F G	H	Į J	<u>к</u>	<u>t</u>
-				 		-	┆┼	_ - -	┿┆	-	-
		Apr 28 1998	3	⊢⊹	+	+	┝╌╂		+	-	+
1. Stephan J. Szyszkoski	, in a field survey on	, 19 do hereb	y state that under 4	۲-	i	- -	9	—1	∔ _ւ՛չ	<u>.</u>	-12
requirements of P.A. 74, Michiga	en P.A. of 1970, the come	er points mentioned in lines 1 and	d 2 above were in 📗						Ш		1
conformence with regulations and United States Department of the that the corner points mentioned	Interior, Bureau of Land M i in lines 3, 4 and 5 above	tanegement or by a decree of a Ćo ware in conformence with the rule	ourt of Lew and for 6 is of the Michigan	 16- 		,	6	 15 	┼╬	•	 -13
Board of Land Surveyors or by recovered, found as expressed by		of Law; established, re-establishe	ed, monumented, '	19	2	۰	21	_22_		3	Ţ
NOTE: Not more than 2 con on this certificate.	ners, all in the same tow	n and range, may be recorded	9 10	30	2	9	28	_ _27_		6	25
			11 12		 	2	33	_34	3!	5	+ -36
			13			l_	Ш	ı	\coprod	i	_

A Description of original monument and accessories and/or subsequent restoration:
(16-Sec. 16) East 1/16 corner, Section 16/st/Corner not established in the original survey. Found no subsequent record.
(4-Sec. 16) Northwest 1/16 corner, Section 16. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(16-Sec. 16) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a line of mean true bearing between Quarter corner 1313.17' West and Section corner 1313.17' East. At the position for the corner I placed a 1" ID x 32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and witnessed by B.Wheeler and D.Lampela, Baraga District Office.

(4-Sec. 16) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite 1/16 corners. At the position for the corner I placed a 1° ID x 32° iron pipe capped with a 4° dia. Cast aluminum MDMR tablet, appropriately stamped. Corner placed and witnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and acc (16) Set I pipe with 4 MDNR cap. 8 lazed and scribed the following: 5 Maple SI1E 23.85 S1/16 8T 8 Maple in clump S64M 33.15 do 6 Maple HO9E 13.25 S1/16 BT 8 M. Birch S88E 31.35 S1/16 BT Placed squared maple post adjacent. Bearings are magnetic. Distances to notch in lower blaze.	essories established to perpetuate locating the (4) Set 1 pipe with 4 MDNR cap. Blazed and scribed the following: 10° Tamarack M80E 17.0° "MNI/16 BT" 8° Cedar S04W 9.0° "MNI/16 BT" 6° Cedar S56M 8.8° "MNI/16 BT" 7° Cedar N07W 20.8° "MNI/16 BT" Bearings are magnetic. Distances to notch in lower blaze. Placed a squared tam. post adjacent.	STEPHAN J. SZYSZKOSKI LAND SKIRVEYOR NO. 33986
L-1 10		CAND COL

Supremar's Michigan Lineage No. 33986

Date 6/10/98

For the Michigan Department of Natural Resources - Forest Management Division