LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Located in: Comer Code # Dublic Land Survey	For corners in			1			
1. Public Land Survey T 18N R 32N L8 T R R S S S S S S S S S S S S S S S S S	Baraga	Located In:	Corner Code #				
2. Property Controlling SIL T88 R 334 15 INScellaneous STR SMiscellaneous STR SMiscellaneous Property in Sec. STR Jun 04 2001 Stephan J. Stystkoski	(County)						
2. Property Controlling S_11 T48, R_32 IS In Section S_T_R 3. Miscollaneous S_T_R 4. Lot No. Recorded Plat 5. Private Claims Jun 04 2001 1. Stephan J. Systkoski	1. Public Land Survey	T48N R 32	W K8				
2. Property Controlling Sil T48 R3W IS In Section S T R Simbollaneous S T R Simbollane		·					
A Description of original monument and accessories and/or subsequent restoration: A Description of original monument and accessories and/or subsequent restoration: B Description of original monument and accessories and/or subsequent restoration: A Description of original monument and accessories and/or subsequent restoration: B Description of original monument and accessories and/or subsequent restoration: B Description of original monument and accessories and/or subsequent restoration: C C Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. B Description of corner evidence found and/or method applied in restoring or resetablishing corner. C Description of corner evidence found and/or method applied in restoring or resetablishing corner. C Description of monument for corner and accessories established to perpetuate localing the position of the corpservation of the corner stream of the lover blaze visible. The Raple, now 12 DBH, is in good condition with scibing visible on lover blaze. C Description of monument for corner and accessories established to perpetuate localing the position of the corpservation of the cor							
3. Miscollaneous S T R Property in Sec. S T R 4. Lot No. Recorded Plat 5. Private Claims Jun 04 2001 (Stephan J. Stysthoski in a Seid survey on 19 de hereby state that under requirements of PA. 74. Mischape PA. of 1970, two corner points mentioned in here is and 2 show were in the treatment of the Mischape PA. of 1970, two corner points mentioned in here is and 2 show were in control of the Mischape PA. of 1970, two corner points mentioned in here is and 2 show were in confirmation of the Mischape PA. of 1970, two corner points mentioned in here is and 2 show were in control of the Mischape PA. of 1970, two corner points mentioned in here is and 2 show were in confirmation of the Mischape PA. of 1970, two corner points mentioned in the corner points mentioned in here is and 2 show were in confirmation of the Mischape PA. Of 1970, the more than 2 corners, all in the seame town and range, may be recorded on this coefficial. A Description of original monument and accessories ancifor subsequent restoration: 3) Quarter corner cosmon to Sections 33-24. Restablished by proportionate assurement in 1971 by A.O. Enger RIS. 1*10x36* iron pipe th 4* alusina cap. N. Sirch is Sect. 22*, Rangel 9 MeV 3.5.*. 5-5ec. 11) Nest 1/1s corner between Sections 11 and 14. Established in 1970 by A.O. Enger RIS sideay and on line between Section and to corners 19,933 ch. west and east. 1*10x36* iron pipe with 4* alusina cap. N. Spruce 5 MoW 36.6*, N. Spruce 5 Store 18.5*. B. Description of corner evidence found and/or method applied in restoring or resetablishing corner: 8) Recovered the 1971 sonusent as described, in good condition, and at record bearing and distance from the 1971 NBTs. The N. Sirch now a cut stup with a seall part of the lover blaze visible. The Raple, now 12* DBH, is in good condition with scibing visible on lover blaze. 9) Found 1*10 Iron pipe with 4* alus (15) Found 1*10 Iron pipe with 4* alusina MOC. cap. Blazed and scribed: 10 cap. Blazed and scribed: 10 cap. Slazed and scribed: 10 cap. Slazed and scri			15				
A. Lot No		S TR					
4. Lot No		s t R					
Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in a sted survey on Jun 04 2001 1. Stephan J. Styszkoski in Jun 04 2001 1. Styszkoski in Jun	, , ,	· —		L	Register of D	eeds Stamp &	File Number
Jun 04 2001 1, Stephan J. Szyszkoski in a fact survey on	4 Lot No. Reco	rded Plat					
Staphan J. Styszkoski , in a field survey on 19 do hereby shire that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformace with neglistions and rules therefore were neglistions and nate therefore were negligible to the Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in common with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented on this certificate. **NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate. **NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate. **NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate. **A Description of original monument and accessories and/or subsequent restoration: **3) Quarter corner cosson to Sactions 27-24. Restablished by proportionate seasuresent in 1971 by A.O. Enger RLS. 1** 1**Dx36** iron pipe that 4** alusinue cap. 1** 1.5					BCD	E F G H	JKL
1. Stephan J. Stystkoski in a fadd survey on 19 do hereby state test under requirements of PA. 74, Michigan P.A. of 1970, the corner points mentioned in less since 2 above were in the corner points mentioned in less since 2 above were in the corner points mentioned in less 3,4 and 5 above were in conformance with the resonance of a count of law and/or that the corner points mentioned in less 3,4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Lew, established, re-established, monumented, recovered, found as expressed below. NOTE: Not more than 2 corners, all in the same bown and range, may be recorded on this cardificate. A. Description of original monument and accessories and/or subsequent restoration: 3) Quarter corner cosson to Sections 33-24. Restablished by proportionate seasuresent in 1971 by A.O.Enger RLS. 1*10x36* iron pipe that 4* alusinus cap. ## sirch 16 SSE 2.2* R. Rapie 9 Noth 35.3*. **Sec. 1.1] Next 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS. alidway and on line between Section and corners 19.933 ch. west and east. 1*10x36* iron pipe with 4* alusinus cap. ## sirch 16 SSE 2.2* R. Rapie 9 Noth 35.3*. **B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 8) Recovered the 1971 sonument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M. Birch now a cut stuap with a saall part of the lower blaze visible. The Maple, now 12* DBH, is in good condition with scibing visible on el lower blaze. **Special Placewered the 1970 sonument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce St is a 12* high stub with scribing visible. The B. Spruce BW is a stuap with notch and scribing visible. Left the sonument [15] Found 1*10 Iron pipe with 4* alus [15]				2	_ {	 	┝╼┇┷┼╌┧┈
requirements of P.A. 74, Mechagen P.A. of 1970, the corner points mentioned in the 1 and 2 shows were in conformance with regulations and rise therefore are regioned in the current mains of accept of the conformance of the public of a Court of the Indick, Bursar of Land Management of by a decicion of a Court of Land of a Court of Land of Court							
Conformance with regulations and nakes therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, not the corresponding to the co	I, Stephan J. Szyszkoski	, in a field survey on	, 19 do hereby sta	ate that under 4	—┆ ─ ┼─┆─		-1,11,2
United States Department of the Interior, Bureau of Land Management or by a docree of a Court of Law end/or that the corner points mentioned in times 3, 4 and 5 above were in conformance with the rises of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-established, monumented, on this certificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 3) Quarter corner cossion to Sections 23-24. Restablished by proportionate assurement in 1971 by A.O.Enger RLS. 1*10x36* iron pipe th 4* alusinus cap. N. 3iron 16 5562; 2.2* R. Restablished by proportionate assurement in 1971 by A.O.Enger RLS. 1*10x36* iron pipe th 4* alusinus cap. N. 3iron 16 5562; 2.2* R. Raple 9 NOM 35.3*. 5-sec. 11) Nest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS. 1*10x36* iron pipe th 4* alusinus cap. 8. Spruce 5 N40M 36.6*, 8. Spruce 5 S30E 18.5*. B. Description of corner evidence found and/or method appiled in restoring or reestablishing corner: 8) Recovered the 1971 anounent as described, in good condition, and at record bearing and distance from the 1971 NBTs. The N. Birch now a cut stupp with a swall part of the lower blaze visible. The Naple, now 12* DBH, is in good condition with scibing visible on a lower blaze. 5-sec. 11) Recovered the 1970 anounent, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce S1 is a 12* high stub with scribing visible. The 8. Spruce BM is a stuap with notch and scribing visible. Left the anounent place and sade new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the comment of the co						+++-	$ \bullet $
Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-established, monumented, a supersect blook as expressed blook. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 8) Quarter corner common to Sections 37-24. Restablished by proportionate assuragent in 1971 by A.O.Enger Rts. 1*10x36* iron pipe th 4* alusinus cap. M.Birch 16 565 E.2.* R.Naple 9 NOH 36.3*. 5-5c. 11) Nest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger Rts. 1*10x36* iron pipe with 4* alusinus cap. B.Spruce 5 NOM 36.6*, B.Spruce 5 S30E 18.5*. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 8) Recovered the 1971 annual as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M.Birch now a cut stump with a swall part of the lower blaze visible. The Haple, now 12* DBH, is in good condition with scibling visible on e lower blaze. 5-5cs. 11) Recovered the 1970 annual time of the condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce ST is a 12* high stub with scribing visible. The 8.Spruce NM is a stump with notch and scribing visible. Left the annual time nounce to the condition of monument for corner and accessories established to perpetuate locating the position of the cognition of t					-1817-	16-15-	14-13-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 3) Quarter corner common to Sections 23-24. Restablished by proportionate assurement in 1971 by A.O. Enger RLS. 1'10x36' iron pipe th 4' alusinus cap. M. Sirch 16 S655 2.2', R. Maple 9 MOM 36.3'. Sec. 11) Next 1/16 corner between Sections 11 and 14. Established in 1970 by A.O. Enger RLS aidway and on line between Section and 4 corners 19.933 ch. west and east. 1'10x36' iron pipe with 4' alusinus cap. B. Spruce 5 N40N 36.6', B. Spruce 5 S30E 18.5'. B. Description of corner evidence found and/or method appNed in restoring or reestablishing corner: B) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The N. Sirch now a cut stump with a small part of the lower blaze visible. The Haple, now 12' DBH, is in good condition with scibing visible on a lower blaze. Sec. 11) Recovered the 1970 monument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce SE is a 12' high stub with scribing visible. The B. Spruce NW is a stump with notch and scribing visible. Left the monument place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new ac	Board of Land Surveyors or by	y a Decree of a Court of L			++++		
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: B) Quarter corner common to Sections 23-24. Restablished by proportionate measurement in 1971 by A.O.Enger RLS. 1"IDx36" iron pipe th 4" aluminus cap. N. Birch 16 565E 2.2", R.Naple 9 NO4M 36.3". 5-Sec. 11) Nest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS midway and on line between Section and 4 corners 19.933 ch. west and east. 1"IDx36" iron pipe with 4" aluminus cap. B. Spruce 5 N40W 36.6", B. Spruce 5 S30E 18.5". B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 8) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The N. Birch now a cut stump with a small part of the lower blaze visible. The Naple, now 12" DBN, is in good condition with scibing visible on e lower blaze. 5-Sec. 11) Recovered the 1970 monument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce SE is a 12" high stub with scribing visible. The 8.Spruce NW is a stump with notch and scribing visible. Left the monument for corner and accessories established to perpetuate locating the position of the common of the com	recovered, found as expressed be	alow:		8	_1920	2122-	23 + 24-
A. Description of original monument and accessories and/or subsequent restoration: 3) Quarter corner conson to Sections 23-24. Restablished by proportionate assurement in 1971 by A.O.Enger RLS. 1*IDx36* iron pipe th 4* aluminus cap. M. Birch 16 S65E 2.2*, R.Raple 9 Mol M.S.3*. 5-Sec. 11) Mest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS midway and on line between Section and 4 corners 19.933 ch. west and east. 1*IDx36* iron pipe with 4* aluminum cap. B.Spruce 5 MoN 36.6*, B.Spruce 5 S30E 18.5*. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M.Birch now a cut stump with a small part of the lower blaze visible. The Maple, now 12* DBH, is in good condition with scibing visible on ellower blaze. 5-Sec. 11) Recovered the 1970 monument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce SE is a 12* high stub with scribing visible. The B.Spruce NM is a stump with notch and scribing visible. Left the monument place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories are as a state of the properties of the p		ners, all in the same town a	and range, may be recorded	1			
A. Description of original monument and accessories and/or subsequent restoration: 3) Quarter corner common to Sections 23-24. Reestablished by proportionate measurement in 1971 by A.O.Enger RLS. 1*10x36* iron pipe th 4* aluminum cap. Whirch 16 Se65 2.2*, R.Maple > Wolw 36.3*. 5-5ec. 1.1) Next 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS midway and on line between Section and 4 corners 19,933 ch. west and east. 1*10x36* iron pipe with 4* aluminum cap. B.Spruce 5 M40M 36.6*, B.Spruce 5 S30E 18.5*. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M.Birch now a cut stump with a small part of the lower blaze visible. The Maple, now 12* DBH, is in good condition with scibing visible on a lower blaze. 5-Sec. 1.1) Recovered the 1970 monument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce ST is a 12* high stub with scribing visible. The B.Spruce NW is a stump with notch and scribing visible. Left the monument place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the common place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locatin	on this certificate.				3029 	2827	-2625
A. Description of original monument and accessories and/or subsequent restoration: 8) Quarter corner common to Sections 23-24. Restablished by proportionate measurement in 1971 by A.O.Enger RLS. 1°10x36° iron pipe th 4° aluminum cap. W.Birch 16 S65E 2.2', R.Maple 9 NO4M 36.3'. 5-Sec. 11) Mest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS midway and on line between Section and 4 corners 19.933 ch. west and east. 1°10x36° iron pipe with 4° aluminum cap. B.Spruce 5 N40M 36.6', B.Spruce 5 S30E 18.5'. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: 8) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M.Birch now a cut stump with a seall part of the lover blaze visible. The Maple, now 12° DBH, is in good condition with scibing visible on a lower blaze. 5-Sec. 11) Recovered the 1970 monument, in good condition, and at record bearing and distance from the remains of the 1970 NBTs. The Spruce SE is a 12° high stub with scribing visible. The B.Spruce NM is a stump with notch and scribing visible. Left the monument place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the cognessiance of the 1970 NBTs. The Spruce SE is a 12° high stub with scribing visible. The B.Spruce NM is a stump with notch and scribing visible. Left the monument place and made new accessories. C. Description of monument for corner and accessories established to perpetuate locating the position of the cognessiance and accessories are aluminum MDDC cap. Blazed and scribed: Sugar No4M 6.4' do 7' Tawarack N40M 43.5' do SZYSZKOSKI NAM 10 NBT 10 10 NBT 10 10 NBT				- 1			
A Description of original monument and accessories and/or subsequent restoration: 1) 4 a Junium cap. M. Birch 16 SSE 2.24. Restablished by proportionate seasurement in 1971 by A.O.Enger RLS. 1*10x36* iron pipe the 4* a Junium cap. M. Birch 16 SSE 2.27, 8.Raple 9 NO4M 36.3*. 5-Sec. 11) Mest 1/16 corner between Sections 11 and 14. Established in 1970 by A.O.Enger RLS midway and on line between Section and 6 corners 19.933 ch. west and east. 1*10x36* iron pipe with 4* aluminum cap. B.Spruce 5 N40M 36.6*, B.Spruce 5 S30E 18.5*. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner. B) Recovered the 1971 monument as described, in good condition, and at record bearing and distance from the 1971 NBTs. The M.Birch now a cut stump with a small part of the lower blaze visible. The Haple, now 12* DBH, is in good condition with scibing visible on a lower blaze. 10 Pound 1 D iron pipe with 4 a lum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* ID iron pipe with 4* Alum (15) Found 1* Alum (15) Found 1* Alum (15) Found 1* Alum					_3132 	33 34	3536
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and accessories established to perpetuate locating the position of the corner and aluminum MOOC cap. Blazed and scribed: STEPHAN J. STEPHAN J. STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986 AND 34ND 33986	8) Recovered the 1971 monum now a cut stump with a sma e lower blaze. 5-Sec. 11) Recovered the 19 Spruce SE is a 12' high stu	ent as described, in good 11 part of the lower bla 70 monument, in good cor b with scribing visible.	od condition, and at record baze visible. The Maple, now	bearing and distar 12" DBH, is in go ng and distance fo	ood condition rom the remai	with scibing	visible on NBTs. The
Sugar N57E 3.3' "1/4S NBT" 6" Tamarack S20E 30.8' "1/16S BT" Sugar S04M 6.4' do 7" Tamarack H40M 43.5' do SZYSZKOSKI LAND "Maple N60M 9.9' do 6" Tamarack N13M 37.8' do LAND "Maple N01E 36.0' (1971 NBT) 8" Tamarack N48E 13.6' do SURVEYOR sarings are magnetic. Distances are to Sq'd tamarack post adjacent. Bearings are magnetic. Distances are to notch in lower blaze. C/L RR tracks bear S35E apx. 75 ft. Signed by Land Sylveyor Date B/15/01						·	
Sugar M57E 3.3' "1/4S MBT" 6" Tamarack S20E 30.8' "1/16S BT" Sugar S04M 6.4' do 7" Tamarack H40M 43.5' do Maple M60W 9.9' do 6" Tamarack N13W 37.8' do "Maple N01E 36.0' (1971 MBT) 8" Tamarack N48E 13.6' do arings are magnetic. Distances are to Sq'd tamarack post adjacent. Bearings tch in lower blaze. C/L RR tracks bear S35E apx. 75 ft. Signed by Steph St			es established to perpetuate lo Found 1 ID iron pipe with 4	cating the position	of the corpus	F M / C W	
Sugar S04M 6.4' do 7" Tamarack M40M 43.5' do 6" Tamarack M40M 43.5' do 6" Tamarack M13M 37.8' do 1AND 1AND 8" Tamarack M48E 13.6' do 1AND 1AND 1AND 1AND 1AND 1AND 1AND 1AND				_	451) m	100	Se.
Maple N60W 9.9' do 6" Tamarack N13W 37.8' do 8" Tamarack N48E 13.6' do SURVEYOR Arings are magnetic. Distances are to Sq'd tamarack post adjacent. Bearings tch in lower blaze. C/L RR tracks bear S35E apx. 75 ft. Signed by Sig							*
"Maple NOIE 36.0' (1971 N8T) arings are magnetic. Distances are to Sq'd tamarack post adjacent. Bearings tch in lower blaze. Signed by STAMARACK N48E 13.6' do Sq'd tamarack N48E 13.6' do Sq'd tamarack post adjacent. Bearings are magnetic. Distances are to notch in lower blaze. C/L RR tracks bear S35E apx. 75 ft. Signed by Signed by Date B/15/01	Maple M60W 9.9'	do 6" Tai		2			
tch in lower blaze. are magnetic. Distances are to notch in lower blaze. C/L RR tracks bear \$35E apx. 75 ft. Signed by Steph C. Supplied Date B/15/01	•			7	SUF	VEYOR /	<u>E</u>
lower blaze. C/L RR tracks bear \$35E apx. 75 ft. Signed by Steph Date B/15/01					1	No. 3986	Ŧ
Signed by Steph Supplied Date 8/15/01	AALL VIL VALLAL MYRES.	lower	blaze. C/L RR tracks bear		10	RYE	•
7/1/22001	Λ				- WOODS	AND SECULATION OF THE PARTY OF	
7/1/22001	- VA	1 1 1 1 2	l. 1.	D-4-	Rlich	01	
	· · —	- J. vyyy	27001	Date	5/15/	-,	

For the Michigan Department of Natural Resources - Forest Management Division