LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code#		
1. Public Land Survey	T 48N R 32W	K8	i	
2. Property Controlling in Section	S T R R S 23 T 48N R 32W S T R	14		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
4. Lot No. , Red 5. Private Claims	corded Plat	(0.1/0.10	A B C D E F G H I J K L	
above were in conformance with r instructions of the United States I a Court of Law and /or that the c	n a field survey on 14 05. 74, Michigan P.A. of 1970, the corner regulations and rules therefore as requipe partment of the Interior, Bureau of corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decree	red in the current manual of s Land Management or by a decr d 5 above were in conformance	and 2 survey 5 cree of 6 ce with 7	
NOTE: Not more than 2 corn on this certificate.	ers, all in the same town and rang	e, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	

A. Description of original monument and accessories and/or subsequent restoration:

(K8) Quarter corner common to Sections 23 and 24. 1852 - Established by Guy H. Carleton Deputy Surveyor midway and on the Section line between Section corners 40.04 chains north and south. Set post. Sugar 12 S39E 12 links, Fir 10 N68W 21 links. 1971 - A.O.Enger RLS reestablished the corner by single proportionate measurement to the original record between Section corners. Set 1"ID I.pipe with 4" aluminum cap. W.Birch 16 S65E 2.2', R.Maple 9 NO4W 36.3'. 2001 - The undersigned recovered the 1971 monument and made additional witnesses. No attempt was made in 2001 to verify the validity of the 1971 position.

(14-Sec. 23) South 1/16 corner between Sections 23 and 24. 1971 - Monumented in 1971 by A.O.Enger RLS. Set 1"IDx36" I.pipe with 4" alum. cap midway and on line between corners 19.995 chains north and south.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K8) Recovered the 1971 monument in accord with the 1971 and 2001 witnesses. Measurements made this date to Section corners north and south show that the position of the monument is grossly erroneous being 66' west of the position intended in 1971. Removed the 1971 monument and reestablished the corner midway and on the section line between Section corners 2633.98' north and south.
- (14-Sec. 23) The 1971 monument was recovered in good condition but was not accepted. The monument occupies a grossly erroneous position N88W 97.9' from the position intended in 1971. Removed the 1971 monument and established the corner midway and on the Section line between Quarter corner 1316.99' north and Section corner 1316.99' south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

)	with 4" alum, MDNR cap.		
measuring nail with	MDNR tag in the side of:	Set measuring nail with M	DNR tag in the side of:
Sugar NO8W 36.1'	mrkd "1/16S NBT"	9" Sugar NO8E 12.4'	mrkd "1/16S BT"
Balsam N88E 37.9'	do	5" Maple N82E 25.75'	do
Sugar S36W 50.5'	do	9" Sugar S20E 18.1'	do
Sugar N85W 63.5'	do	19" Sugar S57W 4.0'	do
	. Bearings are magnetic.	Sq'd cedar post adjacent.	Bearings magnetic.
	measuring nail with Sugar NOBW 36.1' Balsam NBBE 37.9' Sugar S36W 50.5' Sugar NB5W 63.5'	measuring nail with MDNR tag in the side of: Sugar NO8W 36.1' mrkd "1/16S NBT" Balsam N88E 37.9' do Sugar S36W 50.5' do	Sugar NO8W 36.1' mrkd "1/16S NBT" 9" Sugar NO8E 12.4' Balsam N88E 37.9' do 5" Maple N82E 25.75' Sugar S36W 50.5' do 9" Sugar S20E 18.1' Sugar N85W 63.5' do 19" Sugar S57W 4.0'

Signed by

33986

Date

08/16/2010

For the Michigan Department of Natural Resources and Environment, Forest Management

16468

FORM APPROVED BY MICHIGAN STATE BOARD

14. 1975

16469

ed Jan., 1983 Rervised Oct., 1995

STEPHAN J

YSZKOSK LAND