LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #	90
(County)	_		*
1. Public Land Survey	T 49N R 32	• • • •	
2. Property Controlling in Section	S T R S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R		
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number A B C D E F G H I J K L M 2 5 5 4 3 2 1
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the or regulations and rules therefore as Department of the Interior, Burea corner points mentioned in lines 3, d of Land Surveyors or by a I	08/07/13 do hereby state corner points mentioned in lines 1 and 2 required in the current manual of survey at of Land Management or by a decree or 4 and 5 above were in conformance with Decree of a Court of Law; established	7 5 6 6 18 17 16 15 14 13 17 18 18 18 18 18 18 18 18 18 18 18 18 18
NOTE: Not more than 2 corron this certificate.	ners, all in the same town and	range, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original m	nonument and accessories ar	nd/or subsequent restoration:	13

- (F11) Quarter corner common to Sections 28 and 33. 1988 Keith Sackett RLS restored the corner position midway and on line between Section corners. Set 1"x36" iron pipe with 4" aluminum cap. 16" Sugar S70°W 36.9', 3" Cedar S05°E 32.2', 5" Maple N15°E 41.2'.
- (E9) Corner common to Sections 20-21-28-29. 1992 Reestablished by C.E.Hein RLS. Set 3/4" pipe with 2" brass cap 23" a.g. 9" R.Maple N78°E 38.05', 7" R.Maple N25°E 55.43', 6" Balsam S63°E 60.69'.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (F11) Found the 1988 monument in good condition, at record bearing and distance from the Cedar and Sugar NBTs, both in good condition, and substantially at the record position between Section corners. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- (E9) Found the 1992 monument in good condition and at record bearing and distance from the R.Maple NBTs NE, both in good condition. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F11) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 9" Cedar S03°E 32.65' old blazes 1988 NBT 21" Sugar S72°W 37.95' do do 7" Cedar N67°W 7.95' mrkd "1/4S NBT" 6" Spruce N03°E 14.65' do Set sq'd cedar post adjacent.

E= 7899308.786 N= 203548.557

(E9) Found 3/4"ID iron pipe with 2" brass cap. Found the 1992 NBTs as follows:

11" Maple N27°E 55.45' old blazes / nail & tag
12" Maple N80°E 38.05' do do

Set measuring nail with MDNR tag in the side of:
9" Maple S77°E 49.1' mrkd "S28 NBT"
4" Balsam S46°E 53.6' do

Set sq'd cedar post adjacent.
E= 7898546.359 N= 205164.427

Surveyor's Michigan License No.		33986			
	1 070	<u> </u>			
Signed by Stepher	I Smay		Date	09/04/2013	
Coord. Re	ef.=NGS PID RL0	041: N= 21024	16.990 m.	E= 7895426.989 m.	
				meters (NAD83(2011)) Dati

For the Michigan Department of Natural Resources, Forest Resources Division

SZYSZKOSKI LAND SERVEYOR OALA OF PROFESSIONAL SURVEYORS, JALL 28, 1977 33986 perisen May Profession 1983 4 N.D. American, 1995

FORM APPROVED BY MICHIGAN STATE BOA