LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

		**/	1					
Baraga	Located In:	Corner Code #						
(County)								
1. Public Land Survey	T R T R							
2. Property Controlling in Section	S 30 T 49N R 32W S 30 T 49N R 32W S T R	•						
3. Miscellaneous Property in Sec.	S T R S T R		Regis	ster of De	eds Star	mp & File	e Numbe	r
4. Lot No. , Re	corded Plat		A B			G H	I J 1	
5. Private Claims		· · · · · · · · · · · · · · · · · · ·	וווון ז	ŤŤ	i i '	" "	i i '	` ' '
	1 (09/15/2008	2 - 6-	╅╌	┼╌∮╌	 -	┿╌	├ ─ ┆─
ı, Stephan J. Szyszkoski , i	n a field survey on 4	09/17/2008 do hereby state	3 - 7 -	<u> </u>				
		ner points mentioned in lines 1 and 2		<u> </u>	<u> </u>			L i
		equired in the current manual of survey						
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of								
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with								
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				20	 -21 -	 22-	23	24
re-established, monumented, recov	ered, round as expressed below:		9 2		 	┼┼┼	 	
			10-30-	29	2B	-27-	-26-	25
NOTE: Not more than 2 corr	ers, all in the same town and ra	nge, may be recorded	11	 		 -	┼┼┼	
on this certificate.			12-31-	32-	 3 3-	1-34-	35	36

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 30) West 1/16 corner between Sections 19 and 30. Not established in the original survey. 1978 - K.L.Sackett RLS established the corner on line between corners east and west. Set 1" IDx36" iron pipe. 8" Sugar S35E 10.3', 5" Sugar N69E 22.0', 7" Sugar N54W 22.2'.

(4-Sec. 30) Northwest 1/16 corner, Section 30. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: (1-Sec. 30) Found the 1978 monument and accessories in good condition, but 21 ft. west of the proper position. Removed the monument and reestablished the corner on the Section line between Quarter corner 1376.51' east and Section corner 1049.59' west. This position is 20 chains west of the Quarter corner, and 15.25 chains east of the Section corner, proportionate to the dimensions given on the face of the original plat.

(4-Sec. 30) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Sugar N79E 8.9' mrkd "1/16S BT" mrkd "1/16S BT" 10" Sugar NO8W 32.2' 9" Sugar S16E 8.85' dο 6" Sugar N85W 22.55' do 12" Sugar S63W 15.1' do 4" Sugar S31W 19.2' do 10" Sugar N01W 16.9" do 6" Sugar S42E 12.2' do Set sq'd cedar post adjacent. Set sq'd cedar post adjacent. Bearings are magnetic. Bearings are magnetic.

Signed by

Surveyor's Michigan License No. 33986

10/23/2008

For the Michigan Department of Natural Resources, Office of Land and Facilities

16144

FORM APPROVED BY MICHIGAN STATE BOARD

CAND SA Rervised Oct., 1995

STEPHAN J

SURVEYO

YSZKOSK LAND

16145