LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #	4
1. Public Land Survey	T 50N R 33V T 50N R 33V		
2. Property Controlling in Section	S T R S T R		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No. , Red 5. Private Claims	corded Plat		A B C D E F G R I J K L M
	A8	05/23/2011	2 - 6 5 4 3 2 1 - 1
	74, Michigan P.A. of 1970, the co	05/26/2011 do hereby state rner points mentioned in lines 1 and 3	
above were in conformance with regulations and rules therefore as required in the current manual of survey 5			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 60 18 17 16 15 14 13 a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7			
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 80 19 20 21 22 23 24 re-established, monumented, recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			
A Balance of the control			13

A. Description of original monument and accessories and/or subsequent restoration:

(A8) Quarter corner common to Section 19 T50N-R33W and Section 24 T50N-R34W. 1846 - Established by Austin Burt Deputy Surveyor midway and on the Range line between Section corners 40.00 chains north and south. Set Sugar post. Y.Birch 18" S74W 56 links, Y.Birch 18" N78E 14 links. Found no subsequent record.

(A6) Quarter corner common to Section 18 T50N-R33W and Section 13 T50N-R34W. 1846 - Established by Austin Burt Deputy Surveyor midway and on the Range line between Section corners 40.00 chains north and south. Set Cedar post. Y.Birch 10" S10E 32 links, Y.Birch 8" N66W 16 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A8) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the Range line between Section corners 2624.42 north and south, proportionate to the original record.

(A6) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Range line between Section corners 2624.42' north and south, proportionate to the original record.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 4" Sugar S57E 27.3' mrkd "1/4S NBT" 5" Sugar S50W 35.2' do 10" Maple N87W 24.8' do 6" Sugar N52W 30.2' do Set sq'd cedar post adjacent. Bearings are magnetic.

(A6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 17" Hemlock S68E 4.7' mrkd "1/4S NBT" 10" Hemlock S15E 15.4' do 4" Y.Birch S78W 2.6' do 10" Y.Birch N30W 2.3' do Set sq'd cedar post adjacent. Bearings are magnetic.

Date

10/24/2011

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Forest Management Division

16742 16743 FORM APPROVED BY MICHIGAN STATE BOARD

d Jan., 1983 Rervised Oct., 1995

STEPHAN J

LAND SURVEYOR

No. 33986

CAND SA

YSZKOSK