APR 0 8 1996

the following was not of f

COMMISSION		RDATION CERTIFICATE	
(County) 1. Public Land Survey	T 50N R 31W -1	OF DEC AND R	
in Section S 3 . Miscellaneous S	Г R	BARAG/ Regis	A COUNTY REGISTER OF DEEDS ter of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims			A B C D E F G H J K L 2 6 5 4 3 2 4 3 4 7 6 9 10 11 12
Michael Mileski I, , in a field sundo hereby certify that under requirements of Fin lines 1 and 2 above were in conformance with management or by a decree of a Court of Lat 5 above were in conformance with the rules Decree of a Court of Law; established, re-est as expressed below:	P.A. 74, Michigan P.A. of 1970, ti ith regulations and rules therefored ed States Department of the w and/or that the comer points of the Michigan Board of Prof	re as required in the current Interior, Bureau of Land mentioned in lines 3, 4 and essional Surveyors or by a	5
NOTE: Not more than 4 corners, all in the on this certificate.	ne same town and range, ma	y be recorded	11
A. Description of original monument a I-1; Closing Corner common to		·	
See back of form:	P.A. 3 Bara	LAND CORNER 45 OF 1990 ga County 19-95	
B. Description of corner evidence four	nd and/or method applied in	n restoring or reestablishing co	omer:
I-1; Closing Corner common to	Sections 2 and 3, T5	50N, R31W.	
Found a cedar post in the remains of both U.S Accepted as a careful a	S. bearing trees, the c	ondition of each as des	cribed in Part A.
C. Description of monument for come 1-1; Closing Corner common to			position of the corner:
See back of form.	Occuons 2 and 3, 13	014, 1\014V.	MICHAEL D. MILESKI PROFESSIONAL E SURVEYOR

Signed by_ PPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 22, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 Surveyor's Michigan License No. 39091

- A. Description of orginal monument and accessories and/or subsequent restoration:
 - I-1; Closing Corner common to Sections 2 and 3, T50N, R31W.

Originally established during U.S. Survey conducted by Guy Carleton, D.S. in 1850 and monumented with a wood post witnessed by a:

Sugar 10 S60°W 19 lks.

(Recovered as a 36" tall moderately decayed stump approximately 24" in dia. slightly crushed by falling cedars having a hollow lower blaze evident with no remaining marks.)

and a

Hemlock 12 S20°E 53 lks.

(Recovered as a 36" tall severely decayed stump approximately 22" in dia. having a hollow lower blaze displaying axe marks only.)

The late Norman Thompson, R.L.S. #4348 states in his field notes dated 9 September 1947 (copies of which were obtained from the Northern Hardwoods' office in L'Anse) that both U.S. bearing trees were "ok" and that he remonumented the corner with a cedar post and established the following new bearing trees:

Sugar 2 S27°E 11.8' (Gone)

and a

Maple 9 S40°W 16.8'

(Found a 17" dia. standing dead sugar maple having a healed lower face blaze and being slightly windthrown to the southwest.

17.41')

Set 60d spike S/side S38°W

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - i-1; Closing Corner common to Sections 2 and 3, T50N, R31W.

Replaced found cedar post with a 1" (I.D.) x 36" galvanized iron pipe with 2" aluminum cap appropriately stamped as to location.

Set 60d spike	W/side	16" White Spruce	N17°E	36.50'
Set 60d spike	S/side	11" Balsam	N78°E	13.40'
Set 60d spike	E/side	10" Balsam	S03°W	25.32'
Set 60d spike	S/side	9" Sugar Maple	N69°W	27.62

A control point monumented by a ½" x 18" iron rod and cap #39091 bears easterly a distance of 0.74 feet.

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT"