LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga (County)	_ Located In:	Corner Code #		
1. Public Land Survey	T 51N R 3 T 51N R 3	80W C5 80W E4	W	
2. Property Controlling in Section	S T R S T R	4		
3. Miscellaneous Property in Sec.	S T R S T R			
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File	Number
above were in conformance with a instructions of the United States I a Court of Law and /or that the court of the rules of the Michigan Board re-established, monumented, recovery	74, Michigan P.A. of 1970, the regulations and rules therefore a Department of the Interior, Bure corner points mentioned in lines id of Land Surveyors or by a	96	y 5 of 6 18 17 16 15	-11 -12 -14 -13 -23 -24 -26 -25 -35 -36
A. Description of original m		and/or subsequent restoration:	13	

(C5) Corner common to Sections 7-8-17-18. 1846 - Established by Hubbard and Ives, Deputy Surveyors. Set post. Y.Birch 9" S36°E 30 links, Hemlock 10" N17°W 16 links. May 25, 1942 - Norman T. Thompson RLS notes new BTs but makes no mention of original BTs, nor of any monumentation found or set: 1) Maple 7" S05°W 18'6", 2) Maple 7" S82°E 8'2", 3) Maple 6" N73°W 18', 4) Maple 5" N19°E 16'3". Found no subsequent record.

(E4) Quarter corner common to Sections 8 and 9. 1846 - Established by Hubbard and Ives, Deputy Surveyors, midway and on the Section line between Section corners 40.00 chains north and south. Set post. Hemlock 10" S80°E 16 links, Hemlock 10" N50°W 04 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C5) The original post and accessories were not recovered. Found a 1"ID iron pipe, firmly set, and the 1942 witnesses as follows: 1) no evidence; 2) found 10" Sugar with old blaze at record bearing and distance; 3) no evidence; 4) found 7" Sugar, a dead stub, with old blazes facing the pipe, at record bearing and distance. Distances from the pipe to found monuments 5319.69' north (5280' R), and 2611.58' east (2640' R) are reasonable. I accept the pipe as the best available evidence of the position of the original corner.

(E4) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner midway and on the Section line between Section corners 2642.15' north and south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C5) Found 1"ID iron pipe. Set measuring nail with MDNR tag in the side of: 10" Sugar S81°E 8.45' mrkd "S17 NBT" (1942 NBT) 6" Y.Birch S33°W 26.6' mrkd "S18 NBT" 6" Y.Birch S82°W 18.7' do 11" Maple N63°W 3.65' " S7 NBT" Set sq'd cedar post adjacent.	(E4) Set 1"IDx32" I.pipe with 4" Set measuring nail with MDNR tag 4" Sugar N17°E 21.85' mrkd ' 6" Y.Birch S82°E 21.6' 4" Sugar S10°W 20.4' 4" Maple S56°W 13.7'	in the side of	:
E= 7912243.400 N= 227329.355	Set sq'd cedar post adjacent. E= 7913854.395 N= 228116.501		

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011)	Datum Landon Control	
Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.	Datumit of M/C//	
Signed by Stisken I Synstest Date 10/08/2013	* STEPHAN J.	1 100
Surveyor's Michigan License No. 33986	* SZYSZKOSKI LAND	
For the Michigan Department of Natural Resources, Forest Resources Division	SURVEYOR	į
20	TO NO SE	E

PPROVED BY MICHIGAN STATE BOLL OF PHOFESSION STRUCTORS JAN 19