APR 0 8 1996

Surveyor's Michigan License No. 39091

Acres and a second		RECORDATION CERT	
For corners in	Filing Requirem	ent of Act 74, Mich. P.	.A. 1970
Baraga Locate (County)	ed In:	Corner Code #	RECEIVED FOR RECORD THIS 28TH DA OF DECEMBER A.D. 1995 AT 10:30 A
Т	51N R 32W R R	K-13	AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGES 609 - 610.
Т	R R R		Rella J. Robilland BARAGA COUNTY REGISTER OF DEEDS
3. Miscellaneous S T	R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat_			
5. Private Claims			2 6 5 4 3 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
ı, Michael Mileski , in a field survey	on Decembe	er <sub>10</sub> 9	95
do hereby certify that under requirements of P.A in lines 1 and 2 above were in conformance with manual of survey instructions of the United Management or by a decree of a Court of Law a 5 above were in conformance with the rules of Decree of a Court of Law; established, re-established as expressed below:	<ul> <li>74, Michigan P.A. of regulations and rules         States Department and/or that the corne of the Michigan Board lished, monumented,</li> </ul>	of 1970, the corner points ments therefore as required in the control of the Interior, Bureau of the Interior, Bureau of the Interior, Bureau of the Interior, Bureau of the Interior of the I	ationed current 7
NOTE: Not more than 4 corners, all in the on this certificate.	same town and rai	nge, may be recorded	11 12 31 32 33 34 35 36
A. Description of original monument and	daccessories and/	or subsequent restoration	13 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
K-13; Section Corner common to	o Sections 35	and 36, T51N, R32\	N, on 5th Correction Line.
See back of form.	<b>A</b> F	PPROVED LAND CORNER P.A. 345 OF 1990 Baraga County 12-19-95	<u>-</u>
B. Description of corner evidence found	and/or method ap	plied in restoring or reest	tablishing corner:
K-13; Section Corner common to	Sections 35	and 36, T51N, R32V	V, on 5th Correction Line.
Reestablished corner at southwest corner of Sect Section 31, T51N, R31W	tion 35, T51N,	distance along a lati R32W and the sout	itudinal curve between the th one-quarter corner of
•			
C. Description of monument for corner ar	nd accessories est	tablished to perpetuate lo	cating the position of the corner:
K-13; Section Corner common to	Sections 35 a	and 36, T51N, R32V	V, on 5th Correction Line
See back of form.			MICHAEL D. MILESKI PROFESSIONAL SURVEYOR No. 39091

- A. Description of original monument and accessories and/or subsequent restoration:
  - K-13; Section Corner common to Sections 35 and 36, T51N, R32W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Hemlock 7 N43°E 19 lks. (Gone)

and a

Hemlock 6 N46°W 23 lks. (Gone)

This corner was considered to be lost during the course of a survey conducted by Michael Avery and Stephen Douglas of the Bureau of Land Management from 17 September 1982 to 30 September 1983 and approved 8 July 1985. The BLM did not remonument the corner.

The late Norman Thompson, RLS #4348 states in his field notes dated 2 December 1941 (copies of which were obtained from the Northern Hardwoods' office in L'Anse) that "there is a 2" iron pipe, 3 ft long, set in pile rocks for this corner".

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - K-13; Section Corner common to Sections 35 and 36, T51N, R32W, on 5th Correction Line.

Grouted a 1" dia. iron rod with 2" aluminum cap appropriately stamped as to location into a rock knob.

Set 60d spike	W/side	8" Red Maple	N19°E	150.36'
Set 60d spike	NW/side	8" Sugar Maple	N71°E	145.48'
Set 60d spike	N/side	8" Sugar Maple	N87°E	132.30'
Set 60d spike	NW/side	22" Red Maple	S63°W	89.07'
		2" iron pipe	N03°W	46.00'

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT".