

MAY 0 5 1997

Surveyor's Michigan License No. 39091

## I AND CORNER RECORDATION CERTIFICATE

	RECEIVED FOR RECORD THIS 1ST DAY OF NOVEMBER, 1996 AT 10: A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 684-685.  Tello Me Interes	30 EDS
Baraga   Located In:   Corner Code #	DAY OF NOVEMBER, 1996 AT 10: A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 684-685.  The state of the state	30 EDS
T R T R T R T R T R T R T R T R T R T R	RECORDS ON PAGES 684-685.  Telda Me Satyre BARAGA COUNTY REGISTER OF DE	
T	BARAGA COUNTY REGISTER OF DE	
		nber
5. Private Claims	ABCDEFGHIJK	Li
I, Michael Mileski, , in a field survey on October, , 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, recovered, found as expressed below:	2 4 7 8 9 10 11 of a 5 in 6 18 17 16 15 14	-12
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		25
A. Description of original monument and accessories and/or subsequent restoration:	11	-36-
A-6; West One-quarter Corner Section 18, T51N, R33W;		
See back of form.	APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County	
B. Description of corner evidence found and/or method applied in restoring or reestablishing	ing corner: 10-9-96	
A-6; West One-quarter Corner Section 18, T51N, R33W;	and the later was a second	
Accepted the BLM determination that this corner is lost. Found B grading. Reestablished corner on line and at proportionate distance southwest corner of section 18 and the northwest corner of section.	ce from a control traverse between t ion 7. Corner location is at the south	
end of a graded gravel road to the north and 7 feet east of the phacepted as a careful and faithful reestablishment of the position		
	of the original corner.	
Accepted as a careful and faithful reestablishment of the position	of the original corner. the position of the corner:	
Accepted as a careful and faithful reestablishment of the position  C. Description of monument for corner and accessories established to perpetuate locating the	of the original corner. the position of the corner:	
Accepted as a careful and faithful reestablishment of the position  C. Description of monument for corner and accessories established to perpetuate locating the A-6; West One-quarter Corner Section 18, T51N, R33W;  Set a 1"(i.D.) x 36" galvanized iron pipe with a 2" aluminum cap	of the original corner.  the position of the corner:  61.07'  MICHAEL D.  MILESKI  96.22'  96.22'  63.54'  9.39091	
Accepted as a careful and faithful reestablishment of the position  C. Description of monument for corner and accessories established to perpetuate locating the A-6; West One-quarter Corner Section 18, T51N, R33W;  Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap appropriately stamped as to location 12" below the road surface.  i) Set 7" spike NW/side 10" Sugar Maple N44°E  ii) Set 7" spike NE/side 12" Red Maple S34°E  iii) Set 7" spike SE/side 12" Sugar Maple S23°W  iv) Set 7" spike SW/side 14" Yellow Birch N41°W	of the original corner.  the position of the corner:  61.07' 61.0	
Accepted as a careful and faithful reestablishment of the position  C. Description of monument for corner and accessories established to perpetuate locating the A-6; West One-quarter Corner Section 18, T51N, R33W;  Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap appropriately stamped as to location 12" below the road surface.  i) Set 7" spike NW/side 10" Sugar Maple N44°E  ii) Set 7" spike NE/side 12" Red Maple S34°E  iii) Set 7" spike SE/side 12" Sugar Maple S23°W  iv) Set 7" spike SW/side 14" Yellow Birch N41°W  Location Post S06°E	of the original corner.  the position of the corner:  61.07' 57.80' 96.22' 63.54' 35.4' in Part A.  er blaze is scribed	

A. Description of original monument and accessories and/or subsequent restoration:

A-6; West One-quarter Corner Section 18, T51N, R33W;

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Lynn

8

S75°W

31 lks.

and a

Hemlock

9

N33°W

23 lks.

This corner was considered lost and reestablished on line and at proportionate distance between the southwest corner of section 18, T51N, R33W and the northwest corner of section 7, T51N, R33W, both of which are probable U.S. corners, by the Bureau of Land Management during the course of a survey conducted by Stephen Douglas from 10 May 1984 to 10 November 1984 and approved 23 September 1985. The BLM monumented this position with a 9/16" x 30" copperweld and cap stamped as to location and noted the following new hearing trees: the following new bearing trees:

Maple 8 N49°E 93 lks. (61.38')
Found a sugar maple presently alive and 10" in diameter having a mostly healed lower blaze with some scribing visible.

Set 7" spike NW/side

Measured

61 07'

and a

Yellow Birch 10

N38°W

95 lks. (62.70')

Presently alive and 14" in diameter having a mostly open lower blaze with scribing visible.

Set 7" spike SW/side Measured N41°W 63.54'

N44°E

To each of the above BLM new bearing trees I added an upper blaze and painted both blazes red as well as painted a red band around the tree at the upper blaze.

SURVEY & REMONUMENTATION

MAY 0.5 1997

COMMISSION