

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE

COMMI.	SSION Filing Requi	rement of Act 74, Mich. P.A. 1	970						
Baraga (County)	Located In:	Corner Code #	DAY OF A.M. A	RECEIVED FOR RECORD THIS 23RD DAY OF OCTOBER, 1996 AT 10:30 A.M. AND RECORDED IN LIBER 4					
1. Public Land Survey	T <u>51N</u> R <u>33W</u> T R	<u>C-1</u>	OF LAN RECORD						
	T R T R		The	lds	1 17/e	Soul	ye	,	
2. Property Controlling S in Section S	TR TR		BARAGA	COUN	TY REC	GISTER	OF [DEEDS	
3. Miscellaneous S. Property in Sec. S.	TR TR		Register of Deeds Stamp & File Number						
4. Lot No, Record			A R	СЪ	E F	G Н	I J i	K 1. N	
5. Private Claims			2 - 6	5	4-	-3-	2 —		
I, Michael Mileski, in a field survey on October, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3. 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				8	9-	10-	11-	12	
				17		15	-14	13-	
				20		22	26	24	
A. Description of original monu	ment and accessories and/	or subsequent restoration:	11 12 31	32	-33	34-	35	36-	
C-1; Closing Corner comme	on to Sections 5 and	6, T51N, R33W;		A CO	י פעיבה	44/D 0	22.4		
See back of form.					APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County				
B. Description of corner eviden	ice found and/or method a	pplied in restoring or reestablishin	g corner:		10-5	<u> </u>	2	-	
C-1; Closing Corner comme	on to Sections 5 and	6, T51N, R33W;						•	
as described and acce approximately 10 inch the remains of the yel monument to those at	epted by the BLM in 1 nes in diameter bears the How birch U.S. bearing t the other corners list	ly set and projecting 10 incl 984. From this monument 825°E a distance of 3.3 fee g tree proved inconclusive. ted in Part A and their harm	a distinc et. A tho The simil onious re	t stun prough arity d plation	np hole searcl of this ship st	h for rongly			

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1; Closing Corner common to Sections 5 and 6, T51N, R33W;

available evidence of the position of the original corner.

Set a 1"(I.D.) x 36" galvanized iron pipe with a 2" aluminum cap appropriately stamped as to location at the north side of the found iron pipe. The following new bearing trees are in reference to the set iron pipe.

Set 7" spike	E/side	15" Red Maple	S19°E	27.05'
Set 7" spike	NW/side	9" Red Maple	S56°W	30.941
Set 7" spike	N/side	17" White Spruce	N73°W	63.85'
Set 7" spike	SW/side	9* Red Maple	N55°W	53.24'
•		S.C. Sec. 31 & 32	East	9.95'
		Location Post	South	1.0'

MICHAEL D.
MILESKI
PROFESSIONAL
SURVEYOR
No.
39081

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT CC". Both blazes as well as a band around the tree at the upper blaze are painted red.

Signed by _______ Date _____ Date _____ PAGE 676

A. Description of original monument and accessories and/or subsequent restoration:

C-1; Closing Corner common to Sections 5 and 6, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a sugar maple post witnessed by a

Spruce

20

S08°E

05 lks.

and a

Yellow Birch 9

S32°W

11 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was found to be monumented with a 2 inch diameter iron pipe "from which the remains of the orig. bearing trees: A stump hole, bears N. 2°E., 22 lks. dist. (and) A stump hole, bears N. 35°W., 11 lks. dist.". Also during this survey the BLM recovered and accepted similar monuments at the N 1/16 corner common to sections 5 and 6, the one-quarter corner common to sections 5 and 6, and the standard corner common to sections 31 and 32. At the latter two corners the BLM field notes state that the remains of the original bearing trees were recovered. The BLM did not remonument the corner nor did they note any accessories.

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION