SURVEY & REMONUMENTATION

MAY 0.5 1997 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		ng Requirement of Act	74, Mich. P.A. 197	U	
_	COMMISSION			RECEIVED FOR REC	CORD THIS 13TH
Baraga	Located In	: Corner Co] '	DAY OF NOVEMBER,	
(County)				A.M. AND RECORDE OF LAND CORNER F	
1. Public Land Survey	T <u>51N</u> R			RECORDS ON PAGES	
	T R T R			_	
	T R			All of	2 1 to
2. Property Controlling	S T R			RADAKA COUNTY DE	CISTED OF DEEDS
in Section 3. Miscellaneous	S T R S T R			DANAGA COUNTI NE	IGISTER OF DEEDS
Property in Sec.	S T R			Panietar of Dande	Stamp & File Number
			L	Kegister of Decus	Ozamp & The Hamber
4. Lot No , R	ecorded Plat				
5. Private Claims				A B C D E F	G H I J K L M
				2 - 6 - 5 - 4	3 - 1 1
ı, Michael Mileski	, in a field survey or	November , 19	9 _96_ do hereby	3	
state that under requirements	of P.A. 74, Michigan P.A.	of 1970, the corner points n	nentioned in lines 1	4 7 8 9	10 11 12
and 2 above were in conform of survey instructions of the U	nited States Department o	f the Interior, Bureau of Land	Management or by	5	
a decree of a Court of Law a conformance with the rules o				6 18 17 16	15-14-13-
established, re-established, mo	_		o, a doute of Law,	7	
NOTE: Not more than 2 cor	nore all in the came town	and range, may be recorded	l	8 19 20 21	22 23 24
on this certificate.	reis, and the scare town	and range, may be recorded		9	
				10 30 29 28	27 26 25
				11	
A. Description of original	monument and accesso	ories and/or subsequent re	estoration:	12 31 32 33	34 35 36
	_			13	
C-10; One-quarter Co	rner common to Se	ctions 29 and 30, T5	51N, R33W;		LAND CORNER 5 OF 1990
See back o	f form.				a County
oee back of form.				10-7	10-96 10-96
B. Description of corner	evidence found and/or i	method applied in restorin	g or reestablishing o	orner:	·
C-10; One-quarter Co	rner common to Se	ctions 29 and 30, T5	51N, R33W;		
		t east of a fence to t			
	· · · · · · · · · · · · · · · · · · ·	und from a windthrovent a stump hole 18"			
	(Continued on back		iii dianietei is io	cated at approxima	atery 0.5. bearing
	(Tottoniada e,i. bao.	() , (
C. Description of monumer	nt for corner and access	ories established to perpe	tuate locating the p	osition of the corner:	
C-10; One-quarter Cor	rner common to Se	ctions 29 and 30. T5	51N. R33W:		
- · · · · · · · · · · · · · · · · · · ·			,,		2000 1000 MARIE
		e with a 3½" alumin	um cap	- TE	OF MICHIGAN
appropriately s	tamped as to locati	on.		16/	ER.
i) Set 7" spik	e N/side	8" Yellow Birch	S84°E	19.92' * M	ICHAEL D.
ii) Set 7" spik		8" Yellow Birch	S38°E	36.96' # - I PR	OFESSIONAL .
iii) Set 7" spik		6" Sugar Maple	S51°W	25.70'	URVEYOR O
iv) Set 7" spik		10" Red Maple	N57°W	23.10'	No. 39091
		Location Post	North	1.0'	FESSIONAL SUT
li) and liii) are me	arkad with wasar so	d lawer blosse. The	lower blaza is a	orlhood "NIRT"	WALLES TO THE STATE OF THE STAT
		d lower blazes. The nd the tree at the upp			
Dan DidLoo do V	ao a bana arour	dio doo de dio app	are pair		
	_	es and are further de			
Both blazes as w	ell as a band aroun	d the tree at the uppe	er blaze are pain	ted red.	
				_	
Signed by	Well Suns	hel		Date <u>S</u> Pos	1996
Surveyor's Michigan Licens	e No. 39091				

A. Description of original monument and accessories and/or subsequent restoration:

C-10; One-quarter Corner common to Sections 29 and 30, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a sugar maple post witnessed by a

Hemlock

S17°E

32 lks.

and a

Sugar

18

S65°W

8 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was remonumented with a 2½" x 30" aluminum pipe

and cap at "record bearing and dist.; from the remains of the orig. bearing trees:

A hemlock stump hole, bears S.17°E., 32 lks. dist.

A stump hole, bears S.65°W., 8 lks. dist.". And " from this cor., an iron pipe, 3/4 in. diam., firmly set, projecting 12 ins. above the ground, bears N. 18°40.6' W., 0.469 chs. dist.".

The BLM noted the following new bearing trees:

Yellow Birch 7

S37°E

56 lks. (36.96")

Presently alive and 8" in diameter with scribing visible in bark. Set a 7" spike on the SW/side.

Measured

S38°E

36.96

maple 10 N56°W 35 lks. (23.10')
Found a red maple presently alive and 11" in diameter having a healed lower blaze.
Set a 7" spike on the S/side.
Measured

Measured

N57°W

23.10

An iron pipe was recovered 20 November 1981 by Brian Taavola, P.S. #21583. A Land Corner Recordation Certificate filed by Mr. Taavola and recorded 19 February 1982 in Liber 4 page 19 states "Found: 3/4" Iron pipe at approx. corner of old East & South fences".

Mr. Taavola noted the following accessories:

7" Maple	N85°W	7.88'
6" Maple	W°80N	14.90
5" Maple	N18°E	3.95'
5" Y. Birch	East	7.40'
Face of 46"	East	10.0'
Pine Stump		

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- C-10; One-quarter Corner common to Sections 29 and 30, T51N, R33W;

The 3/4" iron pipe recorded by Brian Taavola apparently has been removed. Its position as reestablished from the accessories bears approximately N44°W a distance of 18 feet from the BLM monument. From where Taavola's iron pipe was located a partially down cedar post fence bears to the south and 8 feet to the north this fence bears to the east. There is not a fence corner post. Rather the fence makes the corner around a 4-foot diameter pine stump. Accepted the BLM monument as marking the corner position. I did not remonument the corner but added "PA 345 1996" to the cap. Accepted as the best available evidence of the position of the original corner.

SURVEY& REMONUMENTATION

MAY 0 5 1997

COMMISSION