SURVEY & REMONUMENTATION

FEB 2 3 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION

Baraga (County)	Located in:	Corner Code #	RECEIVED FOR RECORD THIS 3 DAY OF DECEMBER A. D. 1997
1. Public Land Survey	T_52N R_33W TR TR	B-13	10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGE 804-805.
Property Controlling in Section Miscellaneous	TR S T R S T R S T R		Relde Beskops BARAGA COUNTY REGISTER OF DEEDS
Property in Sec.	S TR	·	Register of Deeds Stamp & File Number
I, Michael Mileski that under requirements of P.A. above were in conformance w survey instructions of the Unite decree of a Court of Law and conformance with the rules of testablished, re-established, mon	74, Michigan P.A. of 1970, the co ith regulations and rules therefore d States Department of the Interior /or that the corner points mention	vember _, 19 <u>97</u> do hereby state orner points mentioned in lines 1 and as required in the current manual of a Bureau of Land Management or by led in lines 3, 4 and 5 above were it ors or by a Decree of a Court of Law essed below:	2 4 7 8 9 10 11 12 of a 5 in 6 18 17 16 15 15 15
on this certificate.			10-30-29-28-27-26-25
A. Description of original m	nonument and accessories and/	or subsequent restoration:	11
B-13; South One-quarte	er Corner Section 31, T5:		12 31 33 34 35 36
See back of form	•		APPROVED LAND CORNER PA 345 OF 1990 Baraga County
B. Description of corner e	evidence found and/or method	applied in restoring or reestablish	hing corner: 16-9-47
B-13; South One-quarte	er Corner Section 31, T52	2N, R33W;	
			I by persons unknown. This monument

is close to the single proportioned position. Set a 1"(I.D.) x 36" galvanized iron pipe and cap along the north side of the found iron pipe. No evidence of Mr. Stockly's new bearing trees was found. Accepted as a careful and faithful reestablishment of the position of the original corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- B-13; South One-quarter Corner Section 31, T52N, R33W;

Set a 1" (I.D.) \times 36" galvanized iron pipe with cap stamped as to location projecting 8" above ground.

Set 7" spike	NW/side	10" Red Maple	N22°E	34.851
Set 7" spike	N/side	8" Red Maple	N56°E	33.13'
Set 7" spike	SW/side	10* Red Maple	S63°E	11.21'
Set 7" spike	E/side	6" Red Maple	S26°E	21.10'
	6' Steel fence post w/ yellow sign		North	1'

All of the above new bearing trees are marked with upper and lower blazes.

The lower blaze is scribed "SC NBT". Both blazes and a band around the tree at the upper blaze were painted red.

MICHAEL

MILESKI
PROFESSIONAL
SURVEYOR
No.
39091

LIBER 4 PAGE 804

729 00 ES esc.

SURVEY & REMONUMENTATION

FEB 2 3 1998

SECTION

A. Description of original monument and accessories and/or subsequent restoration:

B-13; South One-quarter Corner Section 31, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Spruce

6

N02°E

22 lks.

and a

Maple

24

N35°W

11 lks.

This corner was reestablished on line at the proportionate distance between original government corners immediately to the east and west by William Stockly on 31 October 1907. Mr. Stockly monumented this corner with a 5" flattened cedar witnessed by a

Yellow Birch 8

S88°E

44 lks.

and a

Hemlock

8

S54°W

17 lks.

This information is from Mr. Stockly's field book No. 15, pages 1549 and 1550, on file at the Michigan Technological University archives.