

MAY 05 The

## CO

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	t ming roods	monitor of Fiot 1 mg monitor 1				
Baraga (County)	Located In:	Corner Code #	RECEIVED F DAY OF OCT A.M. AND R	OBER, 19 ECORDED	96 AT IN LIE	10:30 BER 4
1. Public Land Survey	T <u>52N</u> R <u>33W</u> TR	<u>E-13</u>	OF LAND CO RECORDS ON			
Property Controlling S in Section S.     Miscellaneous S.	TR TR TR TR		Tella BARAGA COU	The a	· /	, シ JF DEEDS
Property in Sec. S.	TR		Register	of Deeds St	amp&F	lle Numbe
4. Lot No, Recorded 5. Private Claims, in that under requirements of P.A. 74, In above were in conformance with resurvey instructions of the United State decree of a Court of Law and /or the conformance with the rules of the Milestablished, re-established, monument NOTE: Not more than 2 corners, also on this certificate.	a field survey on October Michigan P.A. of 1970, the c gulations and rules therefore tes Department of the Interior tat the corner points mentio ichigan Board of Land Surve ted, recovered, found as exp	, 19 <u>96</u> do hereby so orner points mentioned in lines 1 and as as required in the current manual or, Bureau of Land Management or the med in lines 3, 4 and 5 above were yors or by a Decree of a Court of Loressed below;	nd 2 4 7 7 8 9 10 30 11	B E F G	-10	J K L  -2 - 1-  -11 - 12  -14 - 13  -23 - 24  -26 - 25  - 1
A. Description of original monus	ment and accessories and	or subsequent restoration:		32 33	34	35 36
E-13; Standard Corner com	mon to Sections 32	and 33, T52N, R33W;	131	-L		- <u>l l</u>
See back of form.			Ai	APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			shing corner:	10-09-96		
E-13; Standard Corner com	mon to Sections 32	and 33, T52N, R33W;		74	<u>Z</u>	<del></del>
in 1984. From this p	osition a cedar stum	nsistent with the BLM pos p hole approximately 12 to and distance. Also from	to 14 inches in	ned		

in 1984. From this position a cedar stump hole approximately 12 to 14 inches in diameter is located at record U.S. bearing and distance. Also from this location, a raised mound of earth approximately 30 inches in diameter and very much resembling a stump is located at record U.S. bearing and distance. However, an excavation of this mound did not yield any wood fragments. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-13; Standard Corner common to Sections 32 and 33, T52N, R33W;

Set a 1"(I.D.)  $\times$  36" galvanized iron pipe with a 2" aluminum cap appropriately stamped as to location.

Set 7" spike	S/side	10" Yellow Birch	S89°E	17.09
Set 7" spike	NE/side	10" Red Maple	S64°E	63.94
Set 7" spike	E/side	10" White Spruce	S16°W	37.78'
Set 7" spike	W/side	12" Red Maple	N18°W	29.74'
		C.C. Sec. 4 and 5	East	9.24'
		Location Post	South	1.0'



All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT SC". Both blazes as well as a band around the tree at the upper blaze are painted red.

ideal Sucret week	Date 22 027 1996
Surveyor's Michigan License No. 39091	

A. Description of original monument and accessories and/or subsequent restoration:

E-13; Standard Corner common to Sections 32 and 33, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Hemlock

26

N60°E

12 lks.

and a

Cedar

7

N58°W

34 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was "determined at record bearing and dist. from the remains of the orig. bearing trees: A decayed and burnt hemlock stump, size indeterminate, bears N.60°E., 12 lks. dist., with no mks. visible. (and) A decayed and burnt cedar stump, size indeterminate, bears N.58°W., 34 lks. dist., with no mks. visible.". The BLM field notes indicate that this corner was positioned in such a way that the closing corner common to sections 4 and 5, T51N, R33W is located easterly at record U.S. distance (14 lks.) and on the line connecting this standard corner with the nearest recovered and accepted standard corner to the east. That corner being the corner common to sections 33 and 34, T52N, R33W. The BLM did not remonument the corner nor did they note any new bearing trees.

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION