

MAR 3 0 2000

SECTION

Baraga Located fin: Corner Code # FERRINARY A.D. 2000 AT 10:30 A.M.		, v		ER RECORDATION C						
Baraga Located In: Corner Code # FERRURKY A.D. 2000 AT 10.3 Q. M. NND ROCORDED IN LIEBE 5 OF LAND 1. Public Land Survey T.52N R.33W G-7 CORNER RECORDED IN LIEBE 5 OF LAND 1. Public Land Survey T.52N R.33W G-7 CORNER RECORDED IN LIEBE 5 OF LAND 1. Second 1.	For corners in		i mang reedun	rement of Act 14, Mic	1					
1. Public Land Survey T 52N R 33W T R T R T R T R T R T R T R T R T R T R										
2. Property Controlling in Section S T R R R R Representations S T R R R R R R R R R R R R R R R R R R	TR					CORNER RECORDATION RECORDS ON				
4. Lot No	in Section 3. Miscellaneous	S T_ S T_ S T_ S T_	R R		BAR	AGA COUNT	Y REGIST			
5. Private Claims 1. Michgal Mileski , in a field survey on July , 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interiors, Buseau of Land Management or by a decree of a Court of 1 and 1	4. Lot No , 1	Recorded Plat				Register o	t Deeds St	amp&	File Nu	mber
I, Michael Milecki. , in a field survey on July , 18_99 do hereby state that under requirements of PA. 74. Michael PA. 16 1970, the come points mentioned in line at and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Bureau of Land Management or by a decree of a Court of Law and or that the comor points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board or Land Surveyors or by a Decree of a Court of Law; established, re-established, re-e						1 A B C I	E F G	H	JF	LI
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike NE/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	requirements of P.A. 74, Mic conformance with regulation the United States Department and /or that the corner points Michigan Board of Land S	chigan P.A. of 1970, the sand rules therefore a the of the Interior, Bure smentioned in lines 3, surveyors or by a De	ne corner points mer is required in the cui au of Land Managen 4 and 5 above were ecree of a Court (ntioned in lines 1 and 2 abores the manual of survey instruction or by a decree of a Cost in conformance with the second conformation conform	ove were in tructions of ourt of Law rules of the	4 — 7 — 5 5 — 18 — 1 7 — 7	7 16	15	13	1213
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	NOTE: Not more than 2 c	omers, all in the same	town and range, m	av be recorded		9				<u> </u>
A. Description of original monument and accessories and/or subsequent restoration: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike NE/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree				,			928	_27_	-26	
G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) x 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine \$37°W 43.92' Set 7" spike NE/side 8" White Spruce \$85°W 31.47' Set 7" spike NE/side 8" White Spruce \$85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	A. Description of original	el monument and ac	cessories and/or	subsequent restoration	•	``				
See back of form. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	-			·			2 33	—3 4 —	35- 	—36—
 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree 	G-7; Section Corner of	common to Sect	ions 15, 16, 2	1 and 22, T52N, R	33W;	13	<u></u>			 -L
G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) × 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	See back of for	rm.								
The DNR monument set in 1977 has been destroyed. Remonumented this corner from both of the 1977 DNR bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) x 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	B. Description of corner	evidence found and	d/or method applic	ed in restoring or reesta	ablishing corne	er:				
bearing trees. The condition of each is as described in Part A. There are fence lines to the north, east and west. This corner is 9 feet west of the centerline of a north-south, 10-foot wide trail road. Accepted as the best available evidence of the position of the original corner. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) x 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike N/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	G-7; Section Corner of	common to Sect	ions 15, 16, 2	1 and 22, T52N, R	33W;					
G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W; Set a 1" (I.D.) x 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	bearing trees. This corner is 9	The condition of feet west of the	each is as des e centerline of	scribed in Part A. T a north-south, 10-f	here are fer	nce lines to	the north	, east	and w	R /est.
Set a 1" (I.D.) x 36" galvanized iron pipe with cap flush with the ground. Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	C. Description of monur	ment for corner and	accessories estab	olished to perpetuate lo	cating the pos	sition of the co	orrier:			
Set 7" spike SE/side 11" White Spruce N46°E 39.28' Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	G-7; Section Corner of	common to Secti	ons 15, 16, 2	1 and 22, T52N, R3	33W;					
Set 7" spike SE/side 15" Red Pine S37°W 43.92' Set 7" spike N/side 8" White Spruce S85°W 31.47' Set 7" spike NE/side 8" Balsam N40°W 12.84' 6' Steel fence post w/ yellow sign West 2.0' All of the above new bearing trees are marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree	Set a 1" (I.D.) x	36" galvanized	iron pipe with	cap flush with the	ground.					
The lower blaze was scribed "NBT". Both blazes and a band around the tree	Set 7" spike Set 7" spike	SE/side N/side NE/side	15" Red Pine 8" White Spru 8" Balsam	\$37°W ace \$85°W N40°W	43.92' 31.47' 12.84'					
	The lower blaze	was scribed "N	BT". Both bla:			A	STATE OF M	ICHIGA AEL	Park.	

APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County

MILESKI PROFESSIONAL SURVEYOR No. 39091 MOISSIONAL

Date

duribilit a

SECTION

- A. Description of original monument and accessories and/or subsequent restoration:
 - G-7; Section Corner common to Sections 15, 16, 21 and 22, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with a cedar post witnessed by a

15

N77°W

and a

Yellow Birch 15

S32°E

21 lks.

On 13 April 1977, Keith Sackett, PS #19006 found an "old scribed post in line with fences north, east and west and roads south". Mr. Sackett remonumented this corner with a 1" x 36" iron pipe with 4" aluminum cap and noted the following accessories:

4" Maple S66°E 30.7'
Presently alive and 8" in diameter having healed upper and lower blazes.

Measured S69°E 30.5' to face.

13" Maple

N01°E

22.5'

Presently alive and 17" in diameter having healed upper and lower blazes. Measured N03°W 22.3' to face.

An unrecorded land corner recordation certificate prepared by Mr. Sackett is on file at the DNR office in Baraga.