LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #					
(County)							
1. Public Land Survey	T 52N R 33W T 52N R 33W	C7 C6					
2. Property Controlling in Section	S T R S T R						
3. Miscellaneous Property in Sec.	S T R R		Regis	ster of Deed	s Stamp & Fi	ile Number	
4. Lot No. , Re 5. Private Claims	corded Plat		1 A B	CDE	FGH	ΙJΚ	L M
J. Tilvace Claims	C7 12/	03/2007	2 - 6-	+-5-+-	- 43-		-1-
i, Stephan J. Szyszkoski, i that under requirements of P.A.	74, Michigan P.A. of 1970, the corner	03/2007 do hereby state points mentioned in lines 1 and 2	4	8	- 910-	11	_12_
instructions of the United States	regulations and rules therefore as requi Department of the Interior, Bureau of L corner points mentioned in lines 3, 4 and	and Management or by a decree o	(6 1B	17-	-1615-	14	-13-
	rd of Land Surveyors or by a Decree			20-	_2122_	23	-24-
			10-30-	29-	_2827-	26	25
	ners, all in the same town and range	e, may be recorded	11	+	111	+ 1-+	
on this certificate.			12 31-	32-	33 34		
A. Description of original m	nonument and accessories and/or	subsequent restoration:					

- (C7) Corner common to Sections 17-18-19-20. 1849 Established by Wm.A.Burt Deputy Surveyor. Set cedar post. Hemlock 10 N31W 7 links, Hemlock 6 S20E 9 links.
- (C6) Quarter corner common to Sections 17 and 18. 1849 Established by Wm.A.Burt Deputy Surveyor, midway and on the Section line between Section corners 40.00 chains north and south. Set cedar post. Hemlock 30" N2OE 13 links, Hemlock 14" S78W 18 links.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (C7) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between Section corners 5270.5' north and south (80.00 ch. GLO), Quarter corner 2641.62' west (40.00 ch. GLO), and Quarter corner 7963.65' east (120.59 ch. GLO).
- (C6) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner midway and on the Section line between Section corners 2635.25' north and south, being proportionate to the original record.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (C7) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: mrkd "1/4S NBT" 8" Sugar NO1W 17.3' 8" Cedar N55E 20.3' mrkd "S17 NBT" 5" Sugar N70E 25.3' 7" Sugar S15W 29.7' "S20 NBT" do 6" Sugar S40E 2.7' do "S19 NBT" 13" Y.Birch S35W 35.3' "S19 NBT" 6" Sugar N38W 8.2' do 16" Maple S86W 13.2' Set sq'd post adjacent. Bearings magnetic. Set sq'd post adjacent. Bearings magnetic.

Signed by

Surveyor's Michigan License No.

Date

09/03/2008

33986 For the Michigan Department of Natural Resources, Office of Land and Facilities

16116

FORM APPROVED BY MICHIGAN STATE BOARD

No LAND SON sed Jan., 1983

Rervised Oct., 1995

STEPHAN J

SZYSZKOSKI

LAND

SURVEYOR

16117