SURVEY & REMONUMENTATION

APR 2 6 1995

BAY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Jiviivii 531()	For	corners COMMISSIO	1
-------------------------------	-----	-------------------	---

Bay Located In: Corner Code +/ (County) T 13N_B 1. Public Land Survey T _____ R _ R _ R _ Property Controlling T R T in Section R Miscellaneous S T R Property in Sec. S R

	E	
2018101 11.51938 11.51938	ယ	:2
REGISTED OF DEEDS	8 25 #I 195	KECOKOE

Register of Deeds Stamp & File Number

4.	Lot No.	Recorded Plat	
5.	Private Claims		

, in a field survey on October 26 Duane F. Ledy 94 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established re-established monumented re-monumented recovered tound as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

5 10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

Set post 80 chains north of M-5, J. Warmpler, 1821

8" Lynn S 15° E 21 links 23" Ash N 46° W 27 links

Tuscola Co. Surveyor E. Teskey set wood stake at M-3, 1895 12" W Oak N 401/4" W 160 links 1" Maple S 463/4" W 60 links

Witnesses by R.J. Black in 1959, state found I beam 12" deep set by others.

Edmands Eng. survey files show I beam found in May, 1963. Notes state one witness agrees with E.Teskey's 1895 witness (\$ 75° W. 3937' to 18" Maple). Leach survey 1973 uses 5" I beam; L.C.R.C., L002 P39

Recorded Surveys
Edmands Eng. survey No. ELS 2035.55, 1985: L980 P874. Position of this corner N 40° W 22.35' from I beam

<u>Unrecorded Surveys</u> Edmands Eng. survey No. 2208, 1963 Leach File No. C-73-24, 1973

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found "T" iron at surface, no cap

Excavated and found 5" H beam 18" below "T" iron

Found recorded witnesses as follows:

S 30° E 21.7'± (22.2'R) to south bridge wall

Existing monument accepted as best available evidence of the position of the original corner Accepted by Bay County Peer Review Group on October 27, 1994

> APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 27 5 + 5 -Date_

Michael MacDonald P.S

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

Replaced "T" iron with 23/4" Bay County brass cap on 5/8" x 24" rebar in monument box <u>M-3</u>

20' to centerline of Reese Road

S 20° E 22.40' to chiseled "x" in southerly end of headwall

N 10° E 26.92' to top center of guard rail beam

S 45° E 61.10' to nail and tag in utility pole

S 45° E 72.5' to top center of south end of culvert

N 40° W 22.35' to boot spike (15" deep) at approximate centerlines of Reese and German Roads



Surveyor's Michigan License No.

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975