RECORDED

REMON CORNER F.7 WILLIAMS TWO

For corners in	LAND CORNE Filing Requi	ERTIFICATE D. P.A. 1970	· · · · · · · · · · · · · · · · · · ·	
(County)	Located in:	Corner Code #	1999 [DEC 28 P 1: 02
1. Public Land Survey	T <u>14N R 3E</u> T R T R	E-7	Lack	o Tores Darteise STER OF DEEDS OUNTY, MICHIGAN
Property Controlling S in Section S Miscellaneous S Property in Sec. S	T R R R R R R R R R R R R R R R R R R R		Register of Deeds Si	
Lot No, Recorded Plat _ Private Claims			A P C D 5	
I, Jerry L. Jones, in a field survey on June 18	1999 do hereby corti	٠	7 3 C D E	FGHIJK

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, manufactured to manufacture of the properties of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, manufactured to manufacture of the properties of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Α		В	С	D	E I	f (3 1	Н	1,	J	K L	. N
2	L	6		5 -	- 4		- 3	3 _	_ 2	_	1	_
3	┝		-	!-	├	 	-	 	 		-	
4	-	7 -	- 8	3 -	- 9	} -	11	, 0 -	1	-	12	2 +
5		 		 		-	_	 				\dashv
6	_	18 -	† ¹	7 -	1	6 ·	-	15 - '	14	-	- 13	5 1
7		· -		-								\neg
8		9 -	2	()	2			22 ⁻	2	,	24	
10		50 —	L 2	9—	- 28	` -	_ :	27-	- 26		- 25	
11			_	Í		, 				_	<u></u>	
12	- 3	1 _	- 3	2 -	- 3	3 -	- :	34 -	- 35	-	- 36	; -
13 L		<u></u>	L.,				_				щ.	لــــا

- A. Description of original monument and accessories and/or subsequent restoration:
- E-7 Corner common to Sections 16, 17, 20 and 21

Survey by Glo, 1831, set post Survey by Edmands Engineering, 1972, 1976, 1979, 1985, found nail Survey by J. Schafer 1974, 1979, found % pipe LCRC by E. Goss, 1972, found 1/2" bar LCRC by E. Goss, 1972, found nail

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- E-7 Corner common to Sections 16, 17, 20 and 21

Found 1/2" pipe per surveys by Edmands Engineering, J. Schafer, and LCRC by E. Goss

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- E-7 Corner common to Sections 16, 17, 20 and 21

Replaced ½" pipe with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in mon box; and is accepted as the best available evidence of the position of the accepted corner

S 42 Deg E, 50.08', centerline top of fire hydrant S 45 Deg E, 47.98', west rod on top project marker (rec. 47.55' to face) S 45 Deg W, 64.55', nail and disc #43066 W power pole N 55 Deg W, 37.62', chiseled "+" in N end concrete pipe (rec)

Signed by Surveyor's Michigan License No. 1988

Date 109 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 **Bay County**

Michael MacDonald P.S. County Representative

