1999 DEC 28 P 1: 02

Barbers Torla Dis Frence REGISTER OF DEEDS BAY COUNTY, MICHIGAN

REMON CORNER F-5, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich

For corners in	Filing Requir	RTIFICATE P.A. 1970	
(County)	Located in:	Corner Code #	1999 DEC 28 P
1. Public Land Survey	T <u>14N</u> R <u>3E</u> T R T R	F-5	Barber Tores Ow REGISTER OF DEE BAY COUNTY, MICH
Property Controlling S in Section S Miscellaneous S Property in Sec. S	TR TR TR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat _ 5. Private Claims			and a pedagodamp at the raumber

I, <u>Jerry L. Jones</u>, in a field survey on <u>June 18</u>, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

F	`	В	C	D	E	F (3	H	1	J	Kι	. 1
2	F	6 -	- 5	5 -	4		- 3	3 _	- 2	? -	1	-
3		 	-		-	—	 	\vdash	├─			-
4	-	7 -	۶ ا	} -	۶ ا	} -	 10	0 -	1	1 -	1:	2 -
5				 	-	-	-	ļ	 	 		
6	 	8 -	- 1	7 -	16	5	}	15 -	 1.	4 -	13	3 -
7	 	Н						-	-	<u> </u>		
8	1	9 1	20	9 7	2	1 -	- ;	22-	2	3 1	24	1
9									-		H	
10	- 3		- 2	7-	- 28	3 7	- 3	27-	- 26	5 7	- 25	5 -
11	72	,	 	$\overline{}$	77	,		7.4	70	_		
12	ر - ا	' 🕇	- 32	'	– 33	7	- :	4	- 35	' ㅓ	- 36	, ㅓ
13												

- A. Description of original monument and accessories and/or subsequent restoration:
- 1/2 Corner common to Sections 9 and 16

Survey by Glo, 1831, set post Survey by J. Schafer, 1974, 1975, found Survey by Edmands Engineering, 1979, found 5/8" iron Survey by D. Burgin, 1993, found



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- F-5 1/4 Corner common to Sections 9 and 16

Found ½" rod on top of ½" rod at position indicated in surveys by J. Schafer, Edmands Engineering and D. Burgin.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-5 1/4 Corner common to Sections 9 and 16

Replaced 1/2" rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 and set mon box; and is accepted the best available evidence of the position of the accepted corner

S 75 Deg W, 211.82', nail in power pole N 85 Deg E, 229.16', W'ly bolt on North end box culvert

S 85 Deg E, 216.66', chiseled "+" on South end box culvert

S 68 Deg E, 133.01', pk nail in power pole (Rec. as 132.95')

Surveyor's Michigan License No.

Date Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

004

310

APPROVED LAND CORNER MM

Michael MacDonald P.S. County Representative