## SECTION

## REMON CORNER F-7, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE

For Bay	corners in	i mig Kedul	rement of ACI 74, MICh	. P.A. 1970
Day	(County)	Located in:	Corner Code #	1999 DEC 28 P 1: 0;
1. F	Public Land Survey	T <u>14N</u> R <u>3E</u> T R T R	F-7	Lacker of a
ii 3. N F	Property Controlling n Section Miscellaneous Property in Sec. ot No, Recorded Pl	T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R R S T R		REGISTER OF DEEDS  BAY COUNTY, MICHIGAN  Register of Deeds Stamp & File Number
I, Jerr that u lines t in the interio cornel of the monul	Private Claims  Y L. Jones, in a field survey on Jurnder requirements of P.A. 74, Mich and 2 above were in conformanc current manual of survey instructor, Bureau of Land Management or points mentioned in lines 3, 4 and Michigan Board of Land Surveyors mented, re-monumented, recovered E: Not more than 2 corners, recorded on this certification.	e 18, 1999, do hereby certifigan P.A. of 1970, the corner with regulations and rules tons of the United States I by a decree of a Court of L 15 above were in conform or by a Decree of a Court of I, found as expressed below	y points mentioned on herefore as required Department of the aw and/or that the ance with the rules of Law; re-established,	A B C D E F G H   J K L  2 - 6 - 5 - 4 - 3 - 2 - 1  3 - 7 - 8 - 9 - 10 - 11 - 12  5 - 18 - 17 - 16 - 15 - 14 - 13  7 - 8 - 19 - 20 - 21 - 22 - 23 - 24  9 - 30 - 29 - 28 - 27 - 26 - 25  11 - 31 - 32 - 35 - 34 - 35 - 36
A. De	escription of original monument	and accessories and/or s	ubsequent restoration:	13
F-7	¼ Corner common to Section Survey by Glo, 1831, set possurvey by Edmands Engine Survey by J. Schafer, 1978, Survey by Ayres Associates Survey by D. Burgin, 1991, f Survey by Wade-Trim, 1997 LCRC by E. Goss, 1972, four	ns 16 and 21  et ering, 1976, 1987, found found 2" pipe 1982, found 2" pipe ound 1 ½" pinch pipe found 1 ½" pinch pipe		IERRY L. JONES PROFESSIONAL SURVEYOR No. 19838 Shing corner:
B. De	scription of corner evidence fou	nd and/or method applied	I in restoring or reestabli	shing corner:
F-7	1/2 Corner common to Section			
	Found 2* pipe at position ind LCRC by E. Goss.	cated in surveys by Edm	ands Engineering, J. Sc	hafer, Ayres Associates, D. Burgin, Wade-Trim and

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-7 1/2 Corner common to Sections 16 and 21

> Replaced 2" pipe with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 and set mon box and is accepted as the best available evidence of the position of the accepted corner

N 2 Deg E, 44.99', nail and disc in power pole (Rec. as 45.03')
N 45 Deg W, 71.60', SW corner brick planter (light post) (Rec. as 71.55')
S 5 Deg E, 25.92', nail and disc in power pole (Rec. as 26.02')
N 65 Deg E, 106.18', nail and disc in 20" Cottonwood

Surveyor's Michigan License No.

Revised May 14, 1971

Revised Jan., 1983

004

Michael MacDonald P.S. **County Representative**