REMON. COR. G-12, WILLIAMS TWP.

For corners in ECTION	= =	rement of Act 74, Mich	
Bay			1998 BAY
(County)	Located in:	Corner Code #	၂ ၁၉၈
1. Public Land Survey	T <u>14N</u> R <u>3E</u> T R T R T R	G-12	ECORD C - 7 A TER OF DI UNTY, MIC
2. Property Controlling	STR		No 36/ 11 = =
in Section 3. Miscellaneous	\$ TR S TR		2
Property in Sec.	s tR		Register of Deeds Stamp & File Number
4. Lot No, Recorded P	lat		
5. Private Claims			ABCDEFGHIJKLI
I. JERRY JONES, in a field survey on J that under requirements of P.A. 74, Mid lines 1 and 2 above were in conformal in the current manual of survey instruinterior, Bureau of Land Management corner points mentioned in lines 3.4	chigan P.A. of 1970, the corne nce with regulations and rules actions of the United States or by a decree of a Court of	er points mentioned on s therefore as required Department of the Law and/or that the	2

A. Description of original monument and accessories and/or subsequent restoration:

of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established,

NOTE: Not more than 2 corners, all in the same town and range, may be

monumented, re-monumented, recovered, found as expressed below:

G-12 1/4 corner common to Sections 33 and 34

recorded on this certificate.

Survey by Glo, 1830's \pm , set post , Harvey Parke , 1831 Survey by M. Hunter, 1960, found rod Survey by Edmands Engineering, 1972, 1985, 1988, found 3/8" iron Survey by Hunter and Whittier, 1975, 1978, found Survey by Wade-Trim, 1975, 1996, found 3/8" rebar Survey by Ayres Associates, 1985, found Survey by Burgin, 1993 LCRC by E. Goss, 1972, found 3/8" iron

MICHIC BERRY L E.HOP OFESSIONA URVEYCH No. 19838 POFESSION

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- G-12 1/4 corner common to Sections 33 and 34

Found 3/8" rod per surveys by M. Hunter, Edmands Engineering, Hunter and Whittier, Wade-Trim, Ayres Associates, and LCRC by E. Goss.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- G-12 1/4 corner common to Sections 33 and 34

Found 3/8" rod per surveys by M. Hunter, Edmands Engineering, Hunter and Whittier, Wade Trim, Burgin, Ayres Associates and LCRC by E. Gross. Replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in monument box. (Dug 3' found nothing); and is accepted as the best available evidence of the position of the accepted corner.

N 50 Deg W, 30.96', pk nail in power pole (R as 31.01' and as 30.98') S 55 Deg E, 55.81', nail and BC disc in power pole \$ 25 Deg E, 114.36', east end 12" CMP (R as 114.6') S 45 Deg W, 45.62', northeasterly corner, corner fence post

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 6 Aug 98 Michael MacDonald P.S. **County Representative**

igned by	\subseteq	Zewy		ones	Date	8	126/98
			 				

Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

004 148

9

10

11

12 13